

POLK COUNTY CORNER RESTORATION FORM SECTION 12 TOWNSHIP 10 S RANGE 5 W W.M. BLM ID 658565 CORNER County Line Monument DATE 4/14/2011 CORNER RESTORATION FIELD BOOK 200-12 PAGE 4 ____ CONDITION REPORT PREVIOUS RENEWALS / SURVEYS, ETC. X RENEWED CS 2629, 3667, 13143, 13663, 14587, 14661, 15402; ___ UNRECORDED Benton Co. Survey 10157 (134) SURVEYED IN MONUMENT AND ACCESSORIES FOUND (CONDITION AND SOURCE) I found a 2' section of a plow share standing vertically with the top of the plowshare 1' below the ground. The plowshare is cited by BCS 134 as being on the County Line. A fence corner post is 1' southwest. The centerline of a gravel access road is 10' southeast. MONUMENT SET (PROCEDURES AND DESCRIPTION) I referenced the high point of the plow share. I then removed the plowshare and at said high point set a 2" X 30" iron pipe with 2 1/2" brass cap up 6". I layed the plow share beside the iron pipe and cap. **NEW ACCESSORIES** -Power Pole #K12L18 1/2 R5: S69°W, 41.71' to a nail and washer 1' up on the left; set witness tag. I tied to three iron rods and caps set by CS 14661. See the "To Reach" sketch below: -IRC 1: S37°W, 199.37'; IRC down 4" -IRC 2: S78°W; 100.60'; IRC down 2" -IRC 3: N59°W; 162.70'; IRC is flush -I set a carsonite post 1' north of the monument -There were no trees available to use as bearing trees. State Plane Coordinate (ORGN 83/96 (2002) in Int'l Feet) N= 396175.41 ft E= 7489878.89 ft NOTES The state plane coordinates given for this point are the result of ties made during the survey for county project 1021, point #45. See project file for more information. MONUMENT DETAIL • IRC 3 MAG DEC. 18° IRC 20 **POLK** IRC 10 BENTON N. T. S. RESTORATION NO. 710SR 5W 11884 REGISTERED FIRM / AGENCY PROFESSIONAL LAND SURVEYOR Robison Rd. Polk County Surveyors Office 820 S.W. Ash St. Dallas, Oregon 97338 (503) 623 - 9287oREGON JANUARY 15 2002 ERIC T BERRY WITNESS Jim Killian, Roger Ray

Page <u>1</u> of <u>1</u>

RENEWAL 12/11