

OREGON CORNER RESTORATION FORM

Section 1 Township 11S Range 07W

County Benton Date 01/05/90

CORNER DESIGNATION

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. CS # 159

Monument(s) & Accessories Found: (Condition and Source)

Section corner $\frac{36}{21}$ found $\frac{1}{2}$ " Galv. Iron Pipe and 4x4 Painted Post

BT 50" DF Healed face N70° E 30.1 feet

$\frac{1}{4}$ Corner 1 & 2

Found 5/8" Iron Rod buried 12" in field and bent

Found stumps for BTs noted in CS # 159 original BTs erroneous call on Easterly most BT in original notes

Monument Detail

Sketch

Monument Set (Procedures and Description)

Ran random line between found $\frac{1}{4}$ cor. 1 & 2 to found Sec $\frac{36}{21}$. Set corner from this random line. Set N 1/16 on Section line 1 & 2

Set 5/8" X 30 iron rod with plastic cap marked Denison Surveying, Inc.

New Accessories 13" DF S523/4° W 18 $\frac{7}{2}$ ft. Mkd 1/16 S 2 BT

8" DF S731/4° E 14 $\frac{2}{2}$ ft. mkd 1/16 S1 BT

1/16 corner location lies approximately 40 ft East of New N-S fence and South 10-15 ft. from fence corner with fence running to the West. from the new fence.

Location & Comments

Surveyor's Seal

Compass Declination 19 $\frac{1}{2}$ °

Firm/Agency _____

DENISON SURVEY, INC.

Address 720 SW Angle

Newport, OR 97365

Party Chief [Signature]

Notes C.A.D.

Witness CA DENISON

