

C.S. 3992-A see 3992 also

August 26, 1964

ACCESSORY SHEET # 12-946A SHOWING CORNERS SET AND FOUND  
IN SECTIONS 24 AND 25, T14S, R9W, W.M., BENTON COUNTY,  
OREGON

A. Section Corner 13, 14, 23, 24

Found original B.T.'s as follows:

D. Fir bearing N 23 W 24 links  
D. Fir N 24-30 E 25 links  
D. Fir S 14-30 E 97 links  
D. Fir S 42-30 W 23 links

B. 1/4 corner sections 13 and 24

Found original B.T.'s as follows:

40" D. Fir bearing N 65 W 30 links  
26" D. Fir stump S 32 E 54 links

C. Section Corner 23, 24, 25, 26

Found original B.T.'s as follows:

10" D. Fir stub bearing N 60 E 30 links  
16" maple S 43 E 15 links

Corner was restored with 2 1/2" G.I.P. and 3"  
brass cap. New bearing trees marked as follows:

30" D. Fir bearing N 59 E 50 links  
36" D. Fir S 28 E 97 links  
39" D. Fir S 58-30 W 98 links  
34" D. Fir N 41 W 87 links

D. 1/4 corner sections 24 and 25

Found original B.T.'s as follows:

28" D. Fir bearing S 50 W 49 links  
42" D. Fir N 64 W 122 links

E. Section corner 25, 26, 35, 36

Found original B.T. as follows

31" D. Fir stub bearing S 49-30 W 18 links  
All other B.T.'s destroyed

F. Found 1/4 corner sections 25 and 36

Found original B.T.'s, now snags  
Found post and tack in proper position

G. West 1/16 corner sections 13 and 24

AMENDED 9-26-84  
M-61433-84  
SEE C.S. 3992-B

Set by proportional measure  
2 1/2" G.I.P. and 3" brass cap. Bearing trees  
marked as follows:

39" D. Fir bearing N 76 W 39 links  
36" D. Fir S 29 W 131 links

H. West 1/16 corner sections 24 and 25

Set by proportional measure  
2 1/2" G.I.P. and 3" brass cap. Bearing trees  
marked as follows:

28" D. Fir bearing N 75-30 W 51 links  
32" D. Fir S 44-30 W 46 links

J. West 1/16 corner sections 25 and 36

Set by proportional measure  
2 1/2" G.I.P. and 3" brass cap. Bearing trees  
marked as follows:

28" maple bearing N 27-30 W 52 links  
21" maple S 80 W 30 links