

116240140

BENTON COUNTY SURVEYORS OFFICE - CORNER RESTORATION

3511


T. 11 S, R. 6 W, W. B. & M., BENTON COUNTY, OREGON

SECTION 32

REPORTED BY JIM S. PETERSON

TITLE LAND SURVEYOR

DATE 5-5-88



● OFFICIAL CORNER FOUND  
○ CORNER SET

LEGIBLE MARKS ON BEARING OBJECTS

HEALED FACE 1911 BT DISTANCE IS SLOPE	SCRIBING VISIBLE ON BROKEN OFF PIECES OF FACE - 1911 BT	HEALED FACE 1911 BT
KIND <u>FIR STUMP</u>	<u>FIR STUMP</u>	<u>MAPLE</u>
SIZE <u>30"</u>	<u>48"</u>	<u>20"</u>
BEARING <u>S51°10'E</u>	<u>N03°E</u>	<u>S72°35'W</u>
DISTANCE <u>422 FT.</u>	<u>30 1/2 FT.</u>	<u>19.8 FT.</u>
BT TAG POSTED <u>✓</u>	<u>✓</u>	<u>✓</u>

C1/4 CORNER COMMON TO SEC. 32  
IS 5/8" X 60" IRON ROD  
DESCRIBE

ADDITIONAL INFORMATION

THE QUART BOTTLE SET IN 1911 HAS BEEN DESTROYED BY ROAD CONSTRUCTION. THEREFORE I SET 2 IRON RODS (5/8" X 30"), ONE DIRECTLY OVER THE OTHER FOR THE CORNER. I DROVE THE TOP OF THE RODS 1 FOOT BELOW THE ROAD SURFACE.

SET 2 RM'S: 1) 5/8" X 30" IRON ROD, N35°E, 54"  
2) 5/8" X 30" IRON ROD, S12°E, 18"

OVER

OREGON  
JULY 31, 1976  
JIM S. PETERSON  
1084

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR