

148300500

DATE 01/05/2021TOWNSHIP 14 SOUTH, RANGE 8 WEST, WILLAMETTE MERIDIAN; SECTION 8 CORNER SOUTHEAST
DONATION LAND CLAIM N/A CORNER N/A**COMMON CORNER(S):**SOUTHWEST CORNER SECTION 9
NORTHWEST CORNER SECTION 16
NORTHEAST CORNER SECTION 17**RECORDS (INFORMATION IN BOLD ITALICS IS COUNTY STAFFS' INTERPRETATION OF THE RECORD)**

BASED ON EXTENSIVE RESEARCH AND RECOVERY OF EVIDENCE, THIS OFFICE HAS DETERMINED THAT MOST GENERAL LAND OFFICE SURVEYORS IN BENTON COUNTY BEFORE 1890 MEASURED TO THE FACE OF BEARING TREES.

- [01] GENERAL LAND OFFICE (GLO) NOTES BY DENNIS HATHORN, D.S., DATED DECEMBER 5, 1856. *DROVE STAKE IN RIVER AT SECTION CORNER. SET WITNESS POST ON NORTH BANK BEARS NORTH, 150 LINKS (99.00 FEET), FROM WHICH A MAPLE 12" DIA BEARS S70°E, 23 LINKS (15.18 FEET); FIR 24" DIA BEARS N5°W, 55 LINKS (36.30 FEET).*
- [02] BENTON COUNTY SURVEY NO. 292 (OLD NO. 126) FIELD NOTES (FIELD BOOK 10, PAGE 74) BY W. C. GALLOWAY, D.C.S., MARCH 1, 1912. *WITNESS CORNER 1.50 CHAINS (99.00 FEET) NORTH, SET 5/8" ROD. FIR 24" DIA BEARS N68°E, 0.713 CHAINS (47.06 FEET); FIR 24" DIA (GLO BT) BEARS N5°W, 0.55 CHAINS (36.30 FEET), STANDING.*
- [03] BENTON COUNTY CORNER RESTORATION BOOK NO. 1, PAGE 31, BY W. C. GALLOWAY, D.C.S., DATED MARCH 1, 1912. *WITNESS CORNER NORTH, 1.50 CHAINS (99.00 FEET) OF CORNER. SET 5/8" ROD. FIR 24" DIA (CSBT) BEARS N68°E, 0.713 CHAINS (47.06 FEET); FIR 24" DIA (GLO BT) BEARS N5°W, 0.55 CHAINS (36.30 FEET), STANDING.*
- [04] BENTON COUNTY CORNER RESTORATION NO. 2672. *TRANSCRIBED FROM RECORD [03] AND MAY CONTAIN ERRORS AND/OR OMISSIONS.*
- [05] BENTON COUNTY MAP NO. 14-8-00003 BY W. C. GALLOWAY, C.S., DATED APRIL 30, 1918. *5/8" IRON ROD WITNESS CORNER 1.50 CHAINS (99.00 FEET) NORTH. FIR 24" DIA (CSBT) BEARS N68°E, 0.713 CHAINS (47.06 FEET); FIR 24" DIA (GLO BT) BEARS N5°W, 0.55 CHAINS (36.30 FEET), STANDING. REVISIONS MADE 1951: 5/8" IRON ROD CROSSED OUT AND 1/2" X 6' ROD IN 3/4" X 4' PIPE WRITTEN IN; CSBT CROSSED OUT; GLO BT STUMP.*
- [06] BENTON COUNTY SURVEY NO. 1572 (OLD NO. 126) FIELD NOTES (FIELD BOOK 79, PAGE 4) BY W. C. GALLOWAY, C.S., DATED APRIL 18, 1942. *5/8" IRON WITNESS CORNER 1.50 CHAINS (99.00 FEET) NORTH OF NORTHWEST CORNER SECTION 16.*
- [07] BENTON COUNTY MAP NO. 14-8-00006 BY W. C. GALLOWAY, C.S., DATED SEPTEMBER 3, 1942. *5/8" IRON ROD WITNESS CORNER 1.50 CHAINS (99.00 FEET) NORTH. FIR 24" DIA (CSBT) BEARS N68°E, 0.713 CHAINS (47.06 FEET); FIR 24" DIA (GLO BT) BEARS N5°W, 0.55 CHAINS (36.30 FEET), STANDING.*
- [08] BENTON COUNTY SURVEY NO. 2305 FIELD NOTES BY MARTIN L. BEYERLEIN, D.C.S., DATED SEPTEMBER 11, 1951. *WITNESS CORNER. SET 1/2" X 6' ROD IN 3/4" X 4' GALVANIZED PIPE.*
- [09] BENTON COUNTY CORNER RESTORATION BOOK NO. 1, PAGE 31, BY MARTIN L. BEYERLEIN, D.C.S., DATED 1951. *WITNESS CORNER NORTH, 1.50 CHAINS (99.00 FEET) OF CORNER. SET 1/2" ROD IN 3/4" PIPE. FIR 24" DIA (GLO BT) BEARS N5°W, 0.55 CHAINS (36.30 FEET), STANDING.*
- [10] BENTON COUNTY CORNER RESTORATION NO. 2672. *TRANSCRIBED FROM RECORD [09] AND MAY CONTAIN ERRORS AND/OR OMISSIONS.*
- [11] BENTON COUNTY SURVEY NO. 2305 BY MARTIN L. BEYERLEIN, D.C.S., AND CURTIS C. HANSON, C.S., DATED SEPTEMBER, 1951. *WITNESS CORNER FOUND 1.50 CHAINS (99.00 FEET) N0°18'W OF SECTION CORNER.*
- [12] BENTON COUNTY SURVEY NO. 2443 BY CURTIS C. HANSON, C.S., DATED DECEMBER 13, 1952. *5/8" ROD WITNESS CORNER 1.50 CHAINS (99.00 FEET) N0°18'W OF SECTION CORNER. FIR 24" DIA (CSBT) BEARS N68°E, 0.713 CHAINS (47.06 FEET); FIR 24" DIA (GLO BT) BEARS N3°W, 0.55 CHAINS (36.30 FEET).*

FIRM/AGENCY: BENTON COUNTY SURVEYOR'S OFFICE
ADDRESS: 360 S.W. AVERY AVE., CORVALLIS, OR 97333; PH. 541-766-6821
RESEARCH BY: DAVID L. MALONE, P.L.S.
DATA ENTRY BY: SAME

BENTON COUNTY CORNER RESTORATION BOOK NO. 1

C.S. # 126



Sec. cor. to Secs 8, 9, 16, & 17. Tp. 14-8. U.C. cor. N. 150' of cor.
Set ~~5/8"~~ rod. Set 1/2" rod in 3/4" pipe (1143 1111)
Fir 24" in dia. brs. N. 68° E. 713'
" 24" " " " N. 5° W. 555' std.

Witnesses John Spencer, C.C. Birch, W.H. Mottley, 3/1/12.

" # 127

1/4 Sec. cor. on N. of sec. 1. Tp. 14-8. west on 3rd std. // S
Set 3/4" galvanized pipe.
Fir 26" in dia. brs. S. 76° E. 1.262'
Maple 15" " " " S 82° W. 579.42' std. (5.95)

Witnesses, W.J. Cathcart, Ben Thompson, Geo. Vernon. 3/6/12

" # 127

1/4 cor. cor. between secs. 31, 36 Tp. 13-8 & 7
Set stone 6" x 10" x 20" Alder down
Double ash 48" in dia. brs. S. 25° 10' E. 1.310'
Ash 28" " " " S 31° 5' W. 2.570'

Witnesses, W.J. Cathcart, Ben Thompson, Geo. Vernon. 3/5/12.

" # 127

1/4 Sec. cor. on S. of sec. 36. Tp. 13-8.
Set pipe
Fir 12" in dia. brs. N. 81° E. .17' std.
Yew 8" " " " N. 76° W. .218'

Witnesses W.J. Cathcart, Ben Thompson, Geo. Vernon. 3/6/12.

" # 127

1/4 Sec. cor. between Secs. 1, 2 Tp. 14-8. Found orig. stone.
Set 1 1/4" pipe
Fir 26" in dia. brs. N. 34° 10' E. 1.465'
" 24" " " " N. 54° 5' E. 1.846'

Witnesses, Geo. Vernon, S.H. Rycraft, W.J. Cathcart. 3/7/12.

" # 127

1/4 Cor. between ^{secs} 7 and 6 Tp. 14-7 & 8.
Set stone 5" x 8" x 12", 12" under ground. also glass.
Cement N.E. cor. of schoolhouse. S. 31° 12' W. 8.891'
Oak 7" in dia. brs. N. 33° 13' W. 5.360'

Witnesses, Geo. Vernon, W.J. Cathcart, Ben Thompson. 3/9/12

" # 127

Sec. cor. to sec. 1, 6, 7, 12. Tp. 14-7 & 8.
Set stone 6" x 10" x 18" with brick-bats. 12" under surface. (alder stump found)
Double oak. 18" in dia. brs. S. 32° E. 3.870' (Bj. on stump of orig. tree)
Oak 18" " " " S 7° W. 3.284' std.

Witnesses, W.J. Cathcart, Geo. Vernon, & Squire S. Rycraft. 3/5/12

" # 127

Sec. Cor. to secs 1, 2, 11, 12. Tp. 14-8.
Set 1 1/2" binder pipe stump
Fir 40" in dia. brs. N. 73° E. 5.65' std. remarked.
" 24" " " " S. 10° 50' E. 2.891'
" 12" " " " S. 89° 30' W. 5.68' std.
Maple 10" " " " N. 89° 30' W. 6.04' "

Witnesses S.H. Rycraft, Wm. Risley, W.J. Cathcart. 3/10/12

ical
under
65.4700
5.75° 20' N
5.2° 05' W
21' W
18° 26' N
2K 25' last page
Pike N.
1997

9/12

Section corner to Sections 8, 9, 16, and 17, Twp. 14-8, W. C. cor. N. 150
chains of corner

Reestablishment by W. C. Galloway

March 1, 1912

Set 5/8" rod

Fir 24" in diam bears N. 68° E .713 chains

Fir 24" in diam bears N. 5° W .55 chains (standing)

Witnesses John Spencer, C. C. Birch, and W. H. Moltby

Replacement by W. C. Galloway

1951

Set 1/2" rod in 3/4" pipe

Fir tree gone

Stump left