



United States Department of the Interior

BUREAU OF LAND MANAGEMENT
Salem District Office
1717 Fabry Road S.E.
Salem, Oregon 97306

IN REPLY REFER TO:

5460(085)
OR080-TS8-302
Bummer Swamp I Reoffer

Ray Wilson
Benton County Surveyor
360 SW Avery Ave.
Corvallis, OR. 97333

JAN -9 2001

Sir:

This letter is to inform you of changes in monumentation as a result of recent timber sale activity in T. 14 S., R. 8 W.

The following bearing trees have been cut above the scribes, debarked, treated with a preservative solution, and covered with a galvanized metal cap:



1. At the E 1/16 corner common to Sec. 35, T. 14 S., R. 8 W., and Sec. 2, T. 15 S., R. 8 W., a Douglas-fir, 37 inches DBH, bears N 76°W, 37.3 feet distant.
2. At the 1/4 corner common to Sec. 35, T. 14 S., R. 8 W., and Sec. 2, T. 15 S., R. 8 W., a Douglas-fir, 38 inches DBH, bears N 34°E, 26.7 feet distant.

Sincerely,

Artis Marys Peak Field Manager

cc: Frank Tuers
Salem Cadastral

RECEIVED
JAN 10 2001

BENTON COUNTY AVERY FACILITY