

C.S. # 1808

Hardcopy 11-5 #8

also see notes in file

F. B.

11-5

Book 92

ENGINEER
FIELD BOOK
No. 4048

70

C.S. 84 Sec. 12-T11-5
1808 A.N. Locke Cl. 41Beg. of the ~~N.E.~~ E. Cor. of same thence lined thence
to Cl. corners N. 89° 50' W. +1° 10' 5.025

	+ 50'	4.900	
1	+ 2° 30'	4.000	set 1/2" pipe
2	thence S. 8° 48' W.	+ 5° 45'	5 8 48' W. 30.34 = 1597
3	+ 1° 40'	2.769	1/2" pipe
4		.797	

Set 1/2" pipe

Found 1/2" pipes, S. 8° 48' W., bent over, some gone.

From $\Delta 1$

5	+ 2° 33'	3.9322	
6		1.3666	
	set 1" shaft S. lts.	.4545	
7		2.2119	
8		2.5318	
	set 1/4" pipe S. lts	.4545	
9	S. lts. + 6° 27'	6.8227	
	set 1/2" pipe		
10	E lts - 4° 30'	4.758	
11	- 3° 20'	1.388	
12	- 8° 35'	2.921	

Far Linn Asbaryland Sept. 14, 1946
W.G. Rigor Norman Thompson

71

13.920	6.0606	6.859	6.858	3.293
13.860	2.7676	6.061	.760	2.768
27.780	3.2930	.797	6.398	6.061
	.393			.797
	2.990			6.858
				5.0239
				4.8995
				3.9972
		+ 1° 40'	2.769	13.920
		pipe - 5° 35'	3.002	10.038
				23.958

Road #102

662.55		399.62
10.0386 =		299.71
		99.9
7.7795	7.7795	
313.08	313.08	
4.7437	4.7437	
9.007	9.007	
594.46	594.46	
10.0386	10.0386	
1.0314	1.0314	
9.0072	9.0072	
4.7437	4.7437	
4.2635	4.2635	
10.035	10.035	
.069	.069	
9.966	9.966	
4.743	4.743	
5.223	5.223	
4	4	
		4.7433
		1.3757
		2.8880
		9.0070
		4.7437
		4.2633