

CS # 2002

PACIFIC ADDITION
Block 20
Lots 7-20

F. B. 88-53

Book 88

DEPARTMENT
OF THE ARMY

ENGINEERING
FIELD BOOK

NO. 4044

2002

C. S. 362 Pacific Add. Monroe
 Beginning at 1 1/2" pipe E. of Hwy.
 on N. line of Pacific Add.,
 had been hit with bull dozer,
 We corrected same from 1 1/2" shaft
 W. of Hwy. 80.24' S. 89° 50' W. and
 1 1/4" pipe at RR. Spur S. 4° 20' W.
 (Found all three iron at RR. Spur.
 Measured N. 4° 20' W. 50.05 from
 1 1/4" pipe at RR. Spur set spike
 thence N. 83° 58' E. 120.03 3/4" G. pipe
 thence S. 6° 52' E. 50.00 1" pipe
 (lined to 1" pipe at Jop in st.)
 thence N. 6° 02' W. 350 from S. line

For E. A. Weidman Apr. 10, 1948
 Brick Yard Owner; Dave W. Schnappert

1948
 597.88
 1948
 106.2
 85.57
 350.24
 Set 5.24
 1822
 15' pipe
 16" pipe
 sets 5.52
 5.92
 40.54
 300
 30' pipe
 1" pipe
 122.33
 194.65
 350.24
 544.87

Charlie Skinner
 Eugene Trask

92.00
 46.00
 138.00
 40.12
 97.88

1875
 104

1875
 1967.75
 1.80
 21.78
 9.90
 31.58
 562.70
 12.55
 31.38
 15.00
 18.38

H.W.L.