

Reestablishment of Corner to fractional
 Section 28, & 33 T. 11. S. R. 11. W. on left bank
 of Maquina Bay, the bearing trees being
 gone in Order to find the true point
 for Corner, I commenced ^{corner} at the fractional
 sections 33 & 34 in accordance with the
 Original notes of the Survey, I run West
 2.50 chns - thence N. 5° W. 18.07 chns, which
 gives point 18.00 chns North and 4.07
 chains West, which agrees with Stake
 standing and as this corner has always
 been kept up I reestablished the same
 by setting Rail - Round nail 4 feet long
 and Sand Stone 12x10x8 & raised Mound
 from which a fir 20 in in diameter
 bears S. 42° W. 78 feet Dist. Marked
 M. C. B. T. A fir 24 in in diameter bears
 N 41° W. 81 feet Dist. Marked M. C. B. T.

Then as the corner to fractional sections 21 & 28
 on Left Bank of Maquina Bay is also gone
 and as the corner was originally established
 by Traverse line, I run in accordance with
 Original notes N. 5° W. 4.00 chns
 N 24° W. 18 chns - N. 8° E 30.00 chains
 N 35° E 11.50 chains to point for corner to
 fractional sections 27 & 28 which did not
 establish but continued N 35° E 6.00 chains
 N. 40° E. 8.00 chns - N 30° E. 11.20 chns to
 point for corner to fractional sections 27 & 28
 at which point set Sand Stone 12x12x10 inches
 marked M. C. from which a fir 40 in in
 diameter bears S. 49° W. 257 feet distant
 Marked M. C. B. T. A fir 40 in in diameter
 bears N. 19° 30' E. 177 feet distant ^{marked} M. C. B. T.
 As the corner to sections 21. 22. 27 & 28 is gone
 it became necessary to re establish this
 corner in the manner stated, but after
 a great deal of care and examination of all
 the facts, I am satisfied the foregoing is