

C.S. # 504

Hardcopy 10-4 # 10

also see notes in file

F.B. 19-11

2/29-1915 John Harris - M. Hodges C. 46  
 CS #221 - (#220 in Book 77)

F/B 19, P, 11  
 CS #504

#504

Begin at Harris Tract = J. R. M. Williams  
 W. along fence - chain only

① 22.34 Temp point fence is N. 00  
 Set cor. N. 2.00'

27.50	1.439333	187.116
27.547	1.440076	1520
		112
27.50	1.439333	
27.552	1.440144	

3586	2750
830	42717
17930	233
28678	
304	8100
15.00	1.90
1.74	2.00
16.74	3.90
8.329	8.435
8.653	8.479
8.494	
.159	

Measure S. 8.435' from ① For Temp. Key way  
 Set cor. 3/4 pipe S. 1.59' + 1.20' = 2.79'

22.340  
 35.871

Back to ① west  
 ③ 35.390 + 02 Fence + N. 28.35.871  
 + 1.86 Set Cor. + 2.06' @ N. 15.  
 2.06

5.042	4.995
5.804	5.845
	1.840
	2
35.84	
1031	
8.399	
.227	
8.626	
.028	
8.608	

MEASURE S. 5.10' + 4.898' + 3.427' = 3.401' 8.399 fence  
 For temp L. cor. + 1.74' @ W 39.5' set 3/4 pipe  
 Mark Oak 28. N. 86 1/4 E 38.3'

Begin at L. C. 46 - Measure N. along line

15.00	15.000	15.000
2.00 - 4 3/4	1.993	16.993
5.00 - 5	4.951	21.944
5.00 + 11	4.908	26.852
318	318	27.170
	27.170	Temp cor.

86.26  
 0.16  
 86.10