

C.S. # 1590

Hardcopy 10-7 # 11

also see notes in file

F.B. 46-73

6 12 18 24 30 36 42 48 54 60 66 72 78 84 90

73

FB 46 PG. 73 CS. 1590

County Survey 272

Beginning at cor. $\frac{22}{23}$ T10-7

B.S. at back sight, (did not find nail)

a.s. S. 89° 26' E

N. 88° 56' W.

correct 194 S. 33'

(189° 29' W 79.818)

39.909

+ 2' 30" 4.894

+ 50' 2.480

- 1° 10' 4.115

- 1.483

and S. 1096

- 9° .993

- 13° 37' 3.247

- 6° 12' 4.689

- .3285

and S. 191

7 \angle L. 1° 22½' + 4° 02' 3.141

8 + 1° 25' 9.768

9 + 4° 40' 6.520

S. 37° 53' W.

and S. 3075

Set Conc. post 7" x 26"

Cedar 18" S. 40° 06' E 1.820 - 5° 20' = 1.812

19 Fir 8" S. 87° 20' W. 3.386 + 10° = 3.335

Sept. 30, 1942

1590

From Page 35

1/4 cor. bet. 27/26 1 1/2" pipe

Fir 30" S. 31° E. 86 std.

" 15" S. 87° E. 420

" 10" S. 1° 10' E. 488

N. 0° 44' E. 40.245 calc.

22 Fir 50 S. 51° W. 86

27 " 40 N. 32° W. 170

N. 4° 51' W. 79.50

21/22 stake

28/27 Fir 50" N. 41° 20' E. 588

" 12 S. 15° 15' E. 1.047313 321032

" 10 S. 39° W. 435

Nail in N. part of 4" stump

79668
 652
 199336
 499340
 578008
 64983536

Nail

Nail without head
S.W. of 6' fir

79.814

2.765

.3825 S.

.075 N.

3075 S.

3825 S.

6900 S.

109 S.

797 S.

797

797

74

For Victor Plunkett

Sept. 29, 1942

97189
 3,247
 680323
 388756
 194378
 291567

3,157,2683

99415

4689

894735

799320

596490

397660

466156935

99752

3,141

99752

399008 20.282

99752 19.9583

12,532

6264

.0751926

offsets

.075 S.

.109 N.

.034 N.

.799 S. 00955 = 33'

765000

712326

466740

399070

676700

38512

38168

4.889

2.480

4.114

11.483

.981

3.156

4.662

20.282

3.132

9.765

33.179

6.498

39.677

39.907

39.677

.230

N. 88° 56' W.

10		+15° 52'	7.163	S. 371
11		+50'	430	offset S. 375
12	L.R. 1° 54 1/2'	-5° 12'	3,300	109 N. S. 515
13		-7° 20'	4,900	S. 562
14		-12° 03'	5,870	S. 617
			-1,0015	
			and S. 608	
15		0°	4,916	S. 665
16		-2° 25'	6,375	S. 726
17		-9° 35'	1,640	S. 741
18		-18° 37'	.953	S. 750
19		-27° 40'	4,020	S. 784
5 1/2" stake	L.L. 27° 07'	-8° 50'	1,7745	offset .7995

12" Post

Came to 1 1/2" iron pin the 1/4 sec. cor. bet. 27/34. A 1/4" pipe S. 20' & N. 20' Thence N. 0° 31' E.

29588	99182	97797
33	49	587
298764	898634	684589
298764	396728	782376
3286404	4866218	488985
3326	.98604	57406839
19716	164	947687
2572	394426	953
9858	591624	284904
9858	98604	473840
10929236	16071056	952912
88566		60.8621
702		59.8605
177132		7.0015
354764		72.174
35603552		1.617
		1.7745
		98814
		1.7745
		494070
		395256
		691298
890087		691698
1753	45580	1753
267024	1753454430	1753
445040		
628056	136740	
87808	227900	
156081024	319060	
	45380	
	79901740	
27		
0 1/4" pipe		
36" E. from pin 1 1/2"		
39983	0 1/4" pipe	25' N. of 1 1/2" pipe
34		
run N. 0° 31' E.		
1" 2 1/2" pipe		
1 bolt		

March 15, 1943.

39.972
19.972
19.972

N. 0° 32' E. 19.972
N. 89° 36' E. 39.993
39.976

39.9765
39.9765
39.9765

N. 0° 30' E. 40.209