

DRAWING NUMBER
4091

DRAWING NUMBER

DRAWING NUMBER

DRAWING NUMBER
4091

C.S. 4091

Survey For
SIDNEY W. NEWTON

In the Chas. A. Williams D.L.C.-Not. No. 1756
Township 10 South, Range 4 West of W.M.
Benton County, Oregon
Scale: 1" = 100' Jan. 19, 1965

REGISTERED
OREGON
LAND SURVEYOR
Fred I. Lemke
MAY 8, 1988
FRED I. LEMKE
443

15011

