

NW cor Section 10

N. 86° 24' W
2674.36

1/4 cor

RECORD OF SURVEY
FOR HARLEY HENDRIX
IN NW 1/4 SECTION 10
T. 15 S. R. 8 W. W. M.
BENTON CO. ORE.

FIR 48"
(stump)

N 37° 10' E
125.4

SCALE 1" = 200'
DEC. 2, 1978

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Richard W. Fail
OREGON
NOVEMBER 4, 1955
RICHARD W. FAIL
357

N. 0° 08' 15" W 2672.78
1336.39

Co. Rd 1943 521.10
S. 31° 0' 53" E

Co. Rd 1914 7

set 8" rod

East
1989.01

set 8" rod

20 Acs.

set 8" rod

N 20° 17' 30" E 193.21
68.98
N 25° 00' 32" W

N 3° 29' 3" E
99.5

26727
set 5" rods

N. 86° 30' 30" W 1651.17

510.05


1336.39

set 1" iron at 1/4 cor

Ed 3/4 pipe

R.W. FAIL, INC.

LAND SURVEYING
P.O. BOX 638
NEWPORT, OR 97365
OFFICE 265-6103



Jim Blair
Benton County Surveyor
360 SW Avery Lane
Corvallis, Oregon 97330

Dear Jim:

Please find enclosed a copy of a survey I did for Harley Hendrix in Dec. 1974.

Ed Hendricks of Willamette Industries is doing a survey in this area and could not find where this survey had been recorded.

In as much as I do not have the original I trust this print may be of some help.

RECEIVED BY

JUL 22 1981

PUBLIC WORKS DEPT

sincerely,

R. W. Fail
R. W. Fail

NOTE: This survey was accepted through the mail, and filed in it's present status because Dick Fail was the Benton County Surveyor at the time the survey was done. The Benton County Map Standards were not applied in this case.

D. Ingram *di*
Dep. Co. Surveyor

Benton County
Surveyor's Office

C. S. FILE NO. 7302
FILING DATE 8-5-81
FILE SIZE 11x17

di