


**Benton County  
Surveyor's Office**

C.S. FILE NO 10309  
 FILING DATE 6-19-08  
 FILE SIZE 11x17



RECORD OF SURVEY  
 FOR  
**Joe and Darlene Santich**  
 JUNE 10, 2008  
 LOT 8, BLOCK II  
 VINEYARD MOUNTAIN SEVENTH ADDITION  
 NW 1/4 SECTION 11, T11S, R5W, W.M.  
 BENTON COUNTY, OREGON

**Narrative**

The purpose of this survey is to locate existing and replace missing corner monuments of Lot 8, Block 2, Vineyard Mountain Seventh Addition. I replaced the missing angle point in the South line of Lot 8 at record bearing and distance from the Southeast corner, the Southwest corner of Lot 8 is also the point of curve of the Burgundy Drive right-of-way, for control I held the record 60.00 feet from and perpendicular to the West line of Burgundy Drive, I also set one monument on the North line of Lot 8, as shown, between the found Northeast and Northwest corners.

**BASIS OF BEARINGS**

N 89°57'00"E 297.27'  
 (N 89°57'00"E 297.52')

DELTA = (2°25'34")  
 RADIUS = (170.00)  
 ARC = (7.20)  
 CHORD = (N 05°00'34"E  
 (7.20)  
 N 05°00'34"E  
 7.20

DRIVEWAY & LANDSCAPE  
 EASEMENT PER DOCUMENT  
 2003-332866, BENTON  
 COUNTY RECORDS.

**Legend** FD. (5/8" LAG BOLT)  
 NO CAP

- FD. 5/8" IRON ROD WITH YELLOW PLASTIC CAP STAMPED "DEVCO ENG. L.S. 2088" EXCEPT AS NOTED
- ⊗ RECORD MONUMENT NOT FOUND
- SET 5/8" X 30" IRON ROD WITH YELLOW PLASTIC CAP STAMPED "DARRYL HARMS PLS 1079"
- ( ) DATA OF RECORD PER PLAT OF:  
 VINEYARD MOUNTAIN SEVENTH ADDITION

REGISTERED  
 PROFESSIONAL  
 LAND SURVEYOR

*Darryl W. Harms*

OREGON  
 JULY 30, 1976  
 DARRYL W. HARMS  
 1079  
 RENEWAL DATE 6/30/09

DARRYL W. HARMS, P.L.S.  
 720 N.E. GRANGER #1  
 P.O. BOX: 1051  
 CORVALLIS, OR 97339  
 PHONE: (541) 745-3948  
 FAX: (541) 745-3952

