

2273

H. F. CHADLER PROPERTY

in

Section 33, Twp. 13 S., R. 5 W., W. M.

Scale: 1 inch = 6 chains May 21, 1953.

I, Curtis C. Hanson, County Surveyor of Benton County, Oregon, hereby certify that this plat was made May 21, 1953 from maps on file in my office, from County Assessor's aerial photographs and from notes taken on a survey made on May 20, 1953, and that the 2-inch pipe, marking the north-east corner of the Jacob Slagle D.L.C. No. 62, was reset in the location determined by the County Surveyor in 1920.

