

DATE 01/22/2007

TOWNSHIP 10 SOUTH, RANGE 04 WEST, WILLAMETTE MERIDIAN; SECTION 08 CORNER SOUTH 1/4
DONATION LAND CLAIM N/A CORNER N/A

COMMON CORNER(S):
NORTH 1/4 OF SECTION 17

RECORDS (INFORMATION IN BOLD /ITALICS IS COUNTY STAFFS' INTERPRETATION OF THE RECORD)
BASED ON EXTENSIVE RESEARCH AND RECOVERY OF EVIDENCE, THIS OFFICE HAS DETERMINED THAT MOST GENERAL LAND OFFICE SURVEYORS IN BENTON COUNTY MEASURED TO THE FACE OF BEARING TREES.

[01] GENERAL LAND OFFICE (GLO) NOTES BY J. FREEMAN, D.S., DATED JULY 16, 1852. SET A POST FROM WHICH A W. OAK **24" DIA BEARS N72°W, 181 LINKS (119.46 FEET). MAKE TRENCH AS PER INSTRUCTIONS.**

[02] GENERAL LAND OFFICE NOTES OF THE JOHN RODGERS DONATION LAND CLAIM NO. 66 BY DAVID STUMP, D.S., DATED DECEMBER 3, 1854. **CORNER TIED BUT NOT DESCRIBED.**

[03] ANDREW PORTER BOOK OF SURVEYS, PAGE 69, SURVEY NO. 48, BY ANDREW L. PORTER, C.S., DATED OCTOBER 17, 1889. **CORNER TIED, BUT NOT DESCRIBED.**

[04] BENTON COUNTY SURVEY NO. 848 (OLD NO. 188) FIELD NOTES (BOOK 33, PAGE 16) BY W. C. GALLOWAY, C.S., DATED JANUARY 30, 1923. SET **3/4" PIPE AND 3/4" PIPE SOUTH AT RIGHT ANGLE 20 FEET.**

[05] BENTON COUNTY SURVEY NO. 848 (OLD NO. 188) BY W. C. GALLOWAY, C.S., DATED DECEMBER 18, 1922. **3/4" PIPE AND 3/4" PIPE SOUTH AT RIGHT ANGLE 20 FEET.**

[06] BENTON COUNTY CORNER RESTORATION BOOK NO 1, PAGE 165 BY W. C. GALLOWAY, C.S., DATED FEBRUARY 1, 1923. SET **3/4" GALVANIZED IRON PIPE IN CENTER OF ROAD ON LINE FROM THE CORNER TO SECTIONS 7, 8, 17 AND 18 AND THE SOUTHEAST CORNER OF JOHN RODGERS CLAIM NO. 66. SET A 3/4" PIPE SOUTH AT RIGHT ANGLE TO LINE 20 FEET.**

[07] CORNER RESTORATION NO. 32. TRANSCRIBED FROM RECORD [04] AND MAY CONTAIN ERRORS AND/OR OMISSIONS.

[08] BENTON COUNTY MAP NO. 10-4-00010 BY W. C. GALLOWAY, C.S., DATED DECEMBER 18, 1922. **3/4" PIPE. 3/4" PIPE SOUTH AT RIGHT ANGLE 20 FEET.**

NOTES:

THIS IS A MICROSOFT WORD 2000 DOCUMENT NAMED "04240500" CREATED FROM A BOILER PLATE DOCUMENT NAMED "HISTORY", WHICH HAS A STYLESHEET NAMED "CORNER" ATTACHED TO IT.

FIRM/AGENCY: BENTON COUNTY SURVEYOR'S OFFICE
ADDRESS: 360 S.W. AVERY AVE., CORVALLIS, OR 97333; PH. 541-766-6821
RESEARCH BY: BERNARD S. ALTENBACH, ENGINEER/SURVEY TECH.
DATA ENTRY BY: SAME

C.S. #134

Corner To Tps.

T. 9-5	I. 9-4
T. 10-5	T. 10-4

Continued

by W.C. Galloway

Witnesses

Jas. C. Smith and

F.E. DeArmond

Set heart oak stake 12" under the surface about 15' N of Posture fence.
 Remarked trees Ash 12" in dia. bears S. 60° E. 1.33 chs. std.

" 13 " " " S. 20° W. .72 "

Corner To secs. 35, 36 T.P. 9 S. R. 5 W. and 1 & 2 T. 10 S. R. 5 W.

Set $5\frac{1}{8}$ " x 2" x 14" iron 12" under the surface

Set $\frac{1}{2}$ " galv. pipe on T.P. line S. 89° 52' E. 3.32 chs., fence 333.

S. edge of chimney of C.A. Voss' house N. 49° 04' E.

N.W. corner of J. V. Johnson's house S. 7° 15' W. about 40 chs.

N. edge of chimney of E.E. DeArmond's house S. 72° W.

N. " " School house N. 57° 03' W.

$\frac{1}{4}$ sec. corner between secs. 1 and 2 T. 10 S. R. 5 W.

Set a brick flat under a stone 8" x 10" x 12", stone 12" under the surface

Set from correct distance south of T.P. line and a proportional distance

from $\frac{1}{4}$ sec. cor. 80.234 chs. West and $\frac{1}{4}$ sec. cor. 40.248 chs. East

and 40.15 chs. south. (Stone that was found by Polk C.S. was on top of ground.)

Cherry tree 8" in dia. bears S. 6° 25' E. .934 chs.

Apple " 14" " " S. 84° 40' W. .744 "

Oak " 40" " " N. 31° 25' W. 5.010 "

Comb of barn N. 1° 45' W. about 60 chs.

S.W. edge of chimney N. 54° 44' W. about 7.00 chs.

C.S. 188 cont.

by W.C. G.

Witnesses

E.C. Stelmacher

C.L. Williamson

Jan. 31, 1923

Corner to sections 17, 18, 19 & 20 T. 10 S. R. 4 W.

Set Oct. bottle 14" under surface. (May be under part. Nail in Post for)

~~Oct 20" in dia., now 78" bears N. 84° 25' E. 7.22 chs. std. (or~~

~~Comb of house N. 24° 07' E. (Cor. next to 10-19-19 cc. Hansen)~~

S. " ~~School house N. 40° 40' E.~~ Out due to Comp Adair.

S. edge of barn 5.74° 16' E. about 3 Miles distant ✓

~~N.E. cor. of fire place chimney on Dodder's house S. 32° 39' E.~~

N. edge of " " " S. 54° 57' W. ?

$\frac{1}{4}$ sec. cor. bet. secs. 18 & 19 T. 10 - 4

Set 1" galv. pipe stake print dim.

Oak stump S. 45 $\frac{1}{2}$ ° E. 1.02 chs. lower part of blaze found.

Remkd " 20" in dia. bears N. 84 $\frac{1}{2}$ ° W. .98 chs. (B.T. on sep.)

Marked " 12" " " S. 22° W. 3.74 "

$\frac{1}{4}$ sec. corner between secs. 8 & 17 T. 10 - 4

Set 7 $\frac{1}{4}$ " galv. iron pipe in center of road on line from

the corner to sections 7, 8, 17 & 18 and the S.E. cor. of John Rodgers C. 166.

Set a 7 $\frac{1}{4}$ " pipe South of L.P.S. 10 line 20 feet.

Witness C. L. Williamson Feb. 1, 1923.

$\frac{1}{4}$ -Section corner between sections 8 and 17, Twp. 10-4

32

Reestablishment by W. C. Galloway

February 1, 1923

Set $\frac{3}{4}$ " galvanized iron pipe in center of road from the Corner to sections 7, 8, 17 and 18 and the S. E. corner of John Rodgers Cl 66.

Set a $\frac{3}{4}$ " pipe south at right angle to line 20 feet
Witness C. L. Williamson