

104846020

DATE 06/25/2014

TOWNSHIP 10 SOUTH, RANGE 4 WEST, WILLAMETTE MERIDIAN; SECTION 20 CORNER N/A
DONATION LAND CLAIM MONROE HODGES NO. 46 CORNER SOUTHEAST

COMMON CORNER(S):

NONE

RECORDS (INFORMATION IN BOLD ITALICS IS COUNTY STAFFS' INTERPRETATION OF THE RECORD)

BASED ON EXTENSIVE RESEARCH AND RECOVERY OF EVIDENCE, THIS OFFICE HAS DETERMINED THAT MOST GENERAL LAND OFFICE SURVEYORS IN BENTON COUNTY MEASURED TO THE FACE OF BEARING TREES.

[01] GENERAL LAND OFFICE (GLO) NOTES OF THE MONROE HODGES DONATION LAND CLAIM NO. 46 BY M. VANDERPOOL, D.S., DATED FEBRUARY 14, 1854. ***DROVE A CHARRED STAKE AND SET A POST FOR THE TRUE SOUTHEAST CORNER OF SAID CLAIM AROUND WHICH RAISED A MOUND WITH TRENCH AS PER INSTRUCTIONS.***

[02] BENTON COUNTY SURVEY NO. 437 (OLD NO. 188) FIELD NOTES (FIELD BOOK 16, PAGE 37) BY W. C. GALLOWAY, C.S., DATED APRIL 10, 1914. ***1-1/4" PIPE.***

[03] BENTON COUNTY CORNER RESTORATION BOOK NO. 1, PAGE 81 BY W. C. GALLOWAY, NO DATE GIVEN. ***1-1/4" PIPE ALREADY SET.***

[04] BENTON COUNTY CORNER RESTORATION NO. 89. ***TRANSCRIBED FROM RECORD [03] AND MAY CONTAIN ERRORS AND/OR OMISSIONS.***

[05] BENTON COUNTY SURVEY NO. 504 SKETCH BY UNKNOWN DRAFTSMAN, NO DATE GIVEN. ***CORNER NOT DESCRIBED.***

[06] BENTON COUNTY SURVEY NO. 848 (OLD NO. 188 & 221) BY W. C. GALLOWAY, DATED DECEMBER 18, 1922. ***1-1/4" PIPE.***

[07] BENTON COUNTY MAP NO. 10-4-00010 BY W. C. GALLOWAY, C.S., DATED DECEMBER 18, 1922. ***FOUND 1-1/4" PIPE.***

FIRM/AGENCY: BENTON COUNTY SURVEYOR'S OFFICE
ADDRESS: 360 S.W. AVERY AVE., CORVALLIS, OR 97333; PH. 541-766-6821
RESEARCH BY: DAVID L. MALONE, P.L.S.
DATA ENTRY BY: SAME

CORNER RESTORATION BOOK NO. 1

- C. Survey # 187
 1/4 sec. cor. between secs. 14 & 15 Tp. 10 S. R 5 W. W. M.
 3/4" pipe galv. in dia. bears S. 56° 30' E. .88 cks. std.
 " 30" " " S 80° 00' W. .38 " "
 Witnesses Jos. C. Smith, R. E. L. Brown, Robison and Carl Carter Apr. 9, 1914.
- " 187
 Sec. cor. to secs. 15, 16, 21 & 22 Tp. 10-5
 Set 3/4" pipe 4 oaks dead
 Fir 15" in dia. bears N. 63° 05' E. .608 cks.
 " 24" " " S 26° 30' E. .495 "
 " 22" " " N. 73° 50' W. .344 "
 " 22" " " N. 25° 45' W. .196 "
 Witness Carl Carter April 25, 1914.
- " 187
 1/4 sec. cor. between secs. 21 & 22 Tp. 10-5.
 Set a 1 1/4" galv. pipe oak down.
 Fir 36" in dia. bears N. 5° E. .170 cks.
 " 14" " " S. 84° 30' W. .36 " std.
 Witnesses Robison & R. E. L. Brown October 22, 1914.
- " 187
 Sec. cor. to secs. 21, 22, 27 & 28 Tp. 10-5.
 3/4" pipe ^{oaks cor.} Willow ^{down} in dia. bears N. 69° E. .100 cks.
 Hollow " 16" " " S. 54° E. .161 "
 " 6" " " S. 51° W. .19 " std.
 Ash " 9" " " N. 77° 30' W. .170 "
 Witness Carl Carter April 25, 1914.
- " 187
 1/4 sec. cor. between secs. 27 & 28 Tp. 10-5.
 Set 1 1/4" galv. pipe from two stumps.
 Oak 4" in dia. bears N. 16° E. 3.546 cks.
 " 2" " " S. 16 1/2° E. October 23, 1914.
 Witness R. E. L. Brown
- " # 188
 N.E. corner of Monroe Hodges D.L.C. # 46, Tp. 10-4
 Set 1 1/4" galv. pipe Two stumps
 Double Ash 22" in dia. bears N. 59° 10' E. 1.199 cks.
 Witnesses Ward Wilkes April 10, 1914.
- " 188
 S.E. corner of Monroe Hodges D.L.C. # 46 Tp. 10-4
 1 1/4" pipe already set
- Cors. in Park co
 " 189
 N.W. cor. of Croghan Rhodes Cl # 68 Tp. 10-4
 1 3/4" pipe Oak 12" in dia. bears N. 89° 47' W. 3.121 cks. one stamp.
 N.E. cor. of Croghan Rhodes Cl # 68 Tp. 10-4
 Set 1 3/4" pipe 2 stamp holes one stamp.
 S.E. of Amon Ryburn Cl # 67 Tp. 10-4
 Stone already set trees std.
 N.E. cor. of Amon Ryburn Cl # 67 Tp. 10-4
 Stone set.

107 89
S. E. corner of Monroe Hodges **DLC 46**, Twp. 10-4

Reestablishment by W. C. Galloway

1 $\frac{1}{4}$ " pipe already set

Date 4-16-1914