

105100240

CORNER FILE TRACKING

S:\Survey Corners\CORNERS\Templates\Filetrac2.doc
10/04/2010

CORNER NUMBER
105100240

STEP	HISTORY	RESTORATION
Form Prepared, DB	6/14/13	
Field Inspection, DB		
Finish index (count unit)	6/14/13	
Counter Index		
GIS Index Form		
Checked, DB		
Form Edited, DB		
Form Signed, DB		
Authorize Payment, DB		
Archive Digital Files		
Collect Documents		
PDF File		
Copy For Filming		
Scanned (pdf to laserfiche)		
Filmed (Archived), DB		
Filed, DB		

(DB) = Entry needed in database (Access).

COMMENTS:

BENTON COUNTY CORNER HISTORY FORM, PAGE 1 OF 1, 105100240H

DATE 06/14/2013

TOWNSHIP 10 SOUTH, RANGE 5 WEST, WILLAMETTE MERIDIAN; SECTION 30 CORNER WEST 1/4
DONATION LAND CLAIM N/A CORNER N/A

COMMON CORNER(S):
EAST 1/4 CORNER SECTION 25, T. 10 S., R. 6 W.

RECORDS (INFORMATION IN BOLD ITALICS IS COUNTY STAFFS' INTERPRETATION OF THE RECORD)
BASED ON EXTENSIVE RESEARCH AND RECOVERY OF EVIDENCE, THIS OFFICE HAS DETERMINED THAT MOST GENERAL LAND OFFICE
SURVEYORS IN BENTON COUNTY MEASURED TO THE FACE OF BEARING TREES.

**[01] GENERAL LAND OFFICE (GLO) NOTES BY BUTLER IVES, D.S., DATED OCTOBER 12, 1852. SET POST FROM WHICH A MAPLE 4"
DIA BEARS N30°W, 16 LINKS (10.56 FEET); A WILLOW 4" DIA BEARS S88°E, 17 LINKS (11.22 FEET).**

FIRM/AGENCY: BENTON COUNTY SURVEYOR'S OFFICE
ADDRESS: 360 S.W. AVERY AVE., CORVALLIS OR 97333; PH. 766-6821
RESEARCH BY: DAVID L. MALONE, P.L.S.
DATA ENTRY BY: SAME