

105140400

DATE 03/12/2013

TOWNSHIP 10 SOUTH, RANGE 5 WEST, WILLAMETTE MERIDIAN; SECTION 18 CORNER SOUTH 1/4
DONATION LAND CLAIM NONE CORNER NONECOMMON CORNER(S):

NORTH 1/4 SECTION 19

RECORDS (INFORMATION IN BOLD ITALICS IS COUNTY STAFFS' INTERPRETATION OF THE RECORD)

BASED ON EXTENSIVE RESEARCH AND RECOVERY OF EVIDENCE, THIS OFFICE HAS DETERMINED THAT MOST GENERAL LAND OFFICE SURVEYORS IN BENTON COUNTY MEASURED TO THE FACE OF BEARING TREES.

[01] GENERAL LAND OFFICE (GLO) NOTES BY ROBERT ELDER, D.S., DATED MARCH 10, 1853. SET POST FROM WHICH A FIR 18" DIA BEARS S70°W, 329 LINKS (217.14 FEET); A FIR 20" DIA BEARS N44-1/2°E, 294 LINKS (194.04 FEET).

[02] BENTON COUNTY SURVEY NO. 1200 (OLD NO. 134) FIELD NOTES (FIELD BOOK 38, PAGE 52) BY W.C. GALLOWAY, C.S., DATED MARCH 2, 1933. SET 3/8" PIPE AND FIR STAKE AND ROCK. FIR 20" DIA (GLO BT) BEARS N44-1/2°E, 2.94 CHAINS (194.04 FEET) STUMP WITH "B" AND NOTCH; FIR 18" DIA (GLO BT) BEARS S70°W, 3.29 CHAINS (217.14 FEET) STANDING; FIR 22" DIA BEARS N42°15'E, 0.604 CHAINS (39.86 FEET); FIR 6" DIA BEARS N80°45'W, 0.428 CHAINS (28.25 FEET).

[03] BENTON COUNTY CORNER RESTORATION BOOK NO. 1, PAGE 199, BY W.C. GALLOWAY, C.S., DATED MARCH 4, 1933. SET 3/8" PIPE AND ROCK PILE. FIR 20" DIA (GLO BT) BEARS N44-1/2°E, 2.94 CHAINS (194.04 FEET) ROTTING STUMP STANDING; FIR 18" DIA (GLO BT) BEARS S70°W, 3.29 CHAINS (217.14 FEET) STANDING, GOOD CONDITION; MARKED FIR 22" DIA (CSBT) BEARS N42-1/4°E, 0.604 CHAINS (39.86 FEET); MARKED FIR 6" DIA (CSBT) BEARS N80-3/4°W, 0.428 CHAINS (28.25 FEET).

[04] BENTON COUNTY CORNER RESTORATION NO. 215. TRANSCRIBED FROM RECORD [03] AND MAY CONTAIN ERRORS AND/OR OMISSIONS.

[05] BENTON COUNTY MAP NO. 10-5-00006 BY W.C. GALLOWAY, C.S., DATED MARCH 1933. 3/8" PIPE AND ROCK. FIR 20" DIA (GLO BT) BEARS N44-1/2°E, 2.94 CHAINS (194.04 FEET) STUMP; FIR 18" DIA (GLO BT) BEARS S70°W, 3.29 CHAINS (217.14 FEET) STANDING; FIR 22" DIA (CSBT) BEARS N42-1/4°E, 0.604 CHAINS (39.86 FEET); FIR 6" DIA (CSBT) BEARS N80-3/4°W, 0.428 CHAINS (28.25 FEET).

[06] BUREAU OF LAND MANAGEMENT NOTES BY LYNN M. ROSEBERRY, CADASTRAL SURVEYOR, DATED JULY 2, 1963. FOUND 3/8" DIA IRON ROD PROTRUDING 6" ABOVE THE GROUND FROM WHICH A FIR STUMP HOLE (GLO BT) BEARS N44-1/2°E, 294 LINKS (194.04 FEET); A FIR SNAG 35" DIA (GLO BT) BEARS S70°W, 329 LINKS (217.14 FEET) WITH A HEALED BLAZE; A FIR 36" DIA (CSBT) BEARS N42-1/2°E, 60-1/2 LINKS (39.93 FEET) WITH A HEALED BLAZE; A FIR 24" DIA (CSBT) BEARS N80-3/4°W, 43 LINKS (28.38 FEET) WITH A HEALED BLAZE. SET AN IRON POST, 28" LONG, 2-1/2" DIA, 24" IN THE GROUND DIRECTLY OVER IRON ROD AND IN A MOUND OF STONE, 2 FEET BASE, TO TOP, WITH BRASS CAP MARKED "T10S R5W 1/4 S18/S19 1963" FROM WHICH A FIR 36" DIA BEARS S20-3/4°E, 56 LINKS (36.96 FEET) MARKED "1/4 S19 BT".

FIRM/AGENCY: BENTON COUNTY SURVEYOR'S OFFICE
ADDRESS: 360 S.W. AVERY AVE. CORVALLIS OR 97333; PH. 766-6821
RESEARCH BY: DAVID L. MALONE, P.L.S.
DATA ENTRY BY: SAME

CORNER RESTORATION BOOK NO. 1

C.S. Road #1
 M.C. Galloway
 Roy S. Lee
 1930.

Most North N.E. Corner of Bushrod W. Wilson C.I. 64 T. 12-5
 Set a Stone 15 1/2" x 15" x 3"
 Oak 40" in dia. bears N. 4° 30' E. 153 chs.
 " 20" " " S 32° W. 136 "

"
 N.W. Corner of Nicholas Owenby D.L.C. #62 T. 12 S. R. 5 W.
 Found orig. sandstone, set E. 503'
 Referenced by 1/2" iron pipe East 415, 95.03 feet and 1" iron rod W. 2497
 Top of Marys Peak is S. 87° 57 1/2' W. (Bearing from 0.55')

Bellpabin-Damon
 Rod Survey
 July 28, 1929
 Witnesses
 Gordon Bath
 M.C. Galloway

Interior Cor. of James McCoy D.L.C. #60 T. 14 S. R. 6 W.
 Set 3/4" pipe 12" under surface found fir stump and log of oak.
 Marked fir 20" in dia. bears S 73° E 4800 chs.
 " Oak 24" " " S 53° W 5880 "

Most South S.E. Cor. of James McCoy D.L.C. #60 T. 14 S. R. 6 W.
 Set pipe

C.S. 286 in Road
 Survey Summit Col. Line
 by M.C. Galloway
 Witnesses
 Geo. Strauts
 Geo. Gilbert
 Jan. 1929

N.W. corner of Sec. 6 and N.W. corner of Township 11 S. R. 7 W.
 Set 22 gauge gun barrel
 Marked Fir 7" in dia. N. 30° E. 145' = 220 chs.
 " 5" " " N 88° E 74' = 112 "
 " 6" " " S. 53 1/2° W. 9.34 = 141 "
 " 6" " " N. 31 1/2° W. 8.07 = 122 "

C.S. #194 continued
 by M.C. Galloway &
 March 3, 1933.
 Witnesses
 J.C. Smith, E.E. Lakin
 Wm. Coats

1/4 Sec. cor. between Secs. 17 & 20 T. 10 S. R. 5 W.
 Set 1/2" Galv. pipe few sticks near.
 Fir 12" now 36" in dia. N. 35° W. 94 chs. std. measure to cen.
 " 60" " " N. 82° W. 1055 "
 " 26" " " S. 41° E. 161 "

Same as cor. above
 Corner to secs. 17, 18, 19 & 20 T. 10-5
 Set 1/2" Galv. pipe. Found 2 stakes and Fir 30" x 10 1/2" W. 121 for trees gone.
 Mkd. Fir 20" N. 5° W. 1081 chs.
 " 13" N. 51 1/2° E. 310 " std.
 " 24" S. 32° E. 212 "
 " 20" S. 78 1/2° W. 272 "

C.S. 134
 March 4, 1933
 Joe C. Smith
 Emile E. Lakin
 Wm. Butolph

1/4 Section corner bet. Secs. 18 & 19 T. 10-5
 Set 3/8" black pipe and rock pile
 Fir 20" in dia. bears N. 44 1/2° E. 257, Felling's stump std.
 " 18" " " S. 70° W. 329, Standing, good condition.
 Marked " 22" " " N. 42 1/2° E. 604
 " " 6" " " N. 80 1/4° W. #28



1/4-Section corner between sections 18 and 19, Twp. 10-5

Reestablishment by W. C. Galloway

March 4, 1933

Set 3/8" black pipe and rock pile

- Fir 20" in diam bears N 44 1/2° E
- Fir 18" in diam bears S 70° W
- Fir 22" in diam bears N 42 1/4° E
- Fir 6" in diam bears N 80 1/2° W

- 2.94 chains
- 3.29 chains
- .604 chains
- .428 chains

Witnesses Jos. C. Smith, Emile E. Larkins and Wm. Butolph