

106100560

67


BENTON COUNTY SURVEYORS OFFICE - CORNER RESTORATION

3280

10 S, R 7 W, W. B. & M., BENTON COUNTY, OREGON

REPORTED BY Theodore Langton
TITLE Reg. Land Surveyor
DATE June 13, 1984

SECTION 12



● OFFICIAL CORNER FOUND

○ CORNER SET

1/16" CORNER COMMON TO SEC. 12 7
IS 5/8" x 30" rebar
DESCRIBE

ADDITIONAL INFORMATION

yellow cap on rebar stamped
"Northstar PLS 1823", white
fiberglass fence post along-
side. The corner falls S35°W
16.5' from a maple with an
old location tag.

LEGIBLE MARKS ON BEARING OBJECTS			
	Set	Set	
	N 1/16 S 12 BT	N 1/16 S 12 BT	
KIND	D-fir	D-fir	
SIZE	20"	32"	
BEARING	S13 1/2°W	S65°E	
DISTANCE	30.22'	14.22'	
BT TAG POSTED			

OVER

THEODORE LANGTON
REG. LAND SURVEYOR
No. 12345
THEODORE LANGTON
1980