

106140500

DATE 05/15/2019TOWNSHIP 10 SOUTH, RANGE 6 WEST, WILLAMETTE MERIDIAN; SECTION 7 CORNER SOUTH 1/4
DONATION LAND CLAIM N/A CORNER N/A**COMMON CORNER(S):**

NORTH 1/4 CORNER SECTION 18

RECORDS (INFORMATION IN BOLD ITALICS IS COUNTY STAFFS' INTERPRETATION OF THE RECORD)

BASED ON EXTENSIVE RESEARCH AND RECOVERY OF EVIDENCE, THIS OFFICE HAS DETERMINED THAT MOST GENERAL LAND OFFICE SURVEYORS IN BENTON COUNTY MEASURED TO THE FACE OF BEARING TREES.

- [01] GENERAL LAND OFFICE (GLO) NOTES BY ALLECK C. SMITH, D.S., DATED MAY 28, 1857. *SET POST FROM WHICH A FIR 48" DIA BEARS S81°W, 2.90 CHAINS (191.40 FEET); AN OAK 3" DIA BEARS N71°E, 25 LINKS (16.50 FEET).*
- [02] BENTON COUNTY SURVEY NO. 614 (OLD NO. 227) FIELD NOTES (FIELD BOOK 24, PAGE 53) BY BURT WILKES, D.C.S., DATED NOVEMBER 15, 1917. *SET PLOW SHEAR 10" BELOW SURFACE. OAK 8" DIA BEARS N79-1/4°E, 1.080 CHAINS (71.28 FEET); OAK 12" DIA BEARS N42-3/4°E, 1.013 CHAINS (66.86 FEET).*
- [03] BENTON COUNTY CORNER RESTORATION BOOK NO. 1, PAGE 130, BY BURT WILKES, D.C.S., DATED NOVEMBER 24, 1917. *SET PLOW SHEAR 15" UNDER SURFACE FOR CORNER FROM WHICH AN OAK 12" DIA (CSBT) BEARS N42-3/4°E, 1.013 CHAINS (66.86 FEET); AN OAK 8" DIA (CSBT) BEARS N79-1/4°E, 1.080 CHAINS (71.28 FEET).*
- [04] BENTON COUNTY CORNER RESTORATION NO. 335. *TRANSCRIBED FROM RECORD [03] AND MAY CONTAIN ERRORS AND/OR OMISSIONS.*
- [05] BENTON COUNTY MAP NO. 10-6-00003 BY BURT WILKES, D.C.S., DATED NOVEMBER 18, 1917. *PLOW SHEAR 10" BELOW SURFACE. OAK 12" DIA (CSBT) BEARS N42-3/4°E, 1.013 CHAINS (66.86 FEET); OAK 8" DIA (CSBT) BEARS N79-1/4°E, 1.080 CHAINS (71.28 FEET).*
- [06] BENTON COUNTY SURVEY NO. 422 BY BURT WILKES, D.C.S., DATED NOVEMBER 18, 1917. *PLOW SHEAR 15" UNDER SURFACE. OAK 12" DIA (CSBT) BEARS N42-3/4°E, 1.013 CHAINS (66.86 FEET); OAK 8" DIA (CSBT) BEARS N79-1/4°E, 1.080 CHAINS (71.28 FEET).*

FIRM/AGENCY: BENTON COUNTY SURVEYOR'S OFFICE**ADDRESS:** 360 S.W. AVERY AVE., CORVALLIS, OR 97333; PH. 541-766-6821**RESEARCH BY:** DAVID L. MALONE, P.L.S.**DATA ENTRY BY:** SAME

$\frac{1}{4}$ -Section corner between sections 7 and 18, Twp. 10 S. R. 6 W. 381 835

Reestablishment by Burt Wilkes

November 24, 1917

Set plow shear 15" in diam under surface

Oak 12" in diam bears N $42\frac{3}{4}^{\circ}$ E

1.013 chains

Oak 8" in diam bears N $79\frac{1}{4}^{\circ}$ E.

1.080 chains

Witnessed by W. S. Alcorn, Jas. Watson