

CORNER FILE TRACKING

H:\Survey\Corners\Misc\Filetrac.doc
11/23/98

CORNER NUMBER
107100565

NORTHWEST CORNER OF BENTON COUNTY.

STEP	HISTORY	RESTORATION
Form Prepared, DB	N/A	N/A
Field Inspection, DB		N/A
Form Checked, DB		N/A
Form Edited, DB		N/A
Form Signed, DB		N/A
Counter Index		N/A
GIS Index		10-3-08
Authorize Payment, DB		10-3-08
Archive Digital Files		N/A
Collect Documents		N/A
Scanned		N/A
Copy For Filming		
Filed, DB		
Finish index (count unit)		
Filmed (Archived), DB		

GIVE COR. # TO ANDREW.

(DB) = Entry needed in database (Access).

COMMENTS:

107100565

LINCOLN COUNTY CORNER REPORT
NORTHEAST COUNTY BOUNDARY CORNER OF SECTION 12, (10-08)
GCDB 1008700565
LINCOLN COUNTY GEODETIC CONTROL STATION 50COR
SHEET 1 OF 2

1975 WILJO GREEN CS 6271, POLK CO. NO. 4388, BENTON CO. NO. 5934

SET: OREGON STATE BOARD OF FORESTRY PIPE AND CAP 30" IN THE GROUND, FROM WHICH:

- 40" FIR BEARS N 30° E, (NO DISTANCE), POLK CO.
- 12" ALDER BEARS N 78° E, 21.8', POLK CO.
- 28" FIR WITH YELLOW METAL LOCATION POSTER BEARS S 22° W, 67.2', LINCOLN CO.
- NO SUITABLE TREE IN BENTON CO.
- 4" X 4" X 72" WHITE PAINTED CEDAR POST SOUTHEAST 1.0'.

1978 WILJO E. GREEN CS 7963, POLK CO. NO. 5231

FOUND: OREGON STATE BOARD OF FORESTRY PIPE AND CAP, 2 BT'S.

1989 MARK E. STEELE CS 12449, POLK CO. NO. 12079, BENTON CO. NO. 8254

FOUND: 1-1/2" X 33" I.D. GALVANIZED IRON PIPE AND 3" BRONZE CAP, ERRONEOUSLY SET IN BENTON CO. SURVEY NO. 5934.

SET: 1-1/2" X 30" ALUMINUM PIPE, 30" IN THE GROUND, WITH 3-1/2" OREGON STATE DEPARTMENT OF FORESTRY ALUMINUM CAP AND MAGNET, ON SECTIONS 12/1 LINE AND 15.45 CHAINS SOUTH OF THE SECTION CORNER, FROM WHICH:

NEW:

- REMOVED BRONZE CAP FROM FOUND PIPE, BEARS N 42°58' W, 4.38'.
- 56" FIR WITH YELLOW MEAL LOCATION POSTER BEARS N 19° E, 17.4'.
- 14" BARK SCRIBED ALDER BEARS N 60° E, 19.8'.
- 32" FIR BEARS S 51° W, 66.5'.
- 4" X 4" X 72" WHITE PAINTED CEDAR POST SOUTHWEST 1.0'.
- THE POLK/BENTON COUNTY LINE WAS BLAZED AND POSTED S 84°57'51" E.

1992 MARK E. STEELE CS 13867, POLK CO. NO. 12592

FOUND: 1-1/2" X 30" ALUMINUM PIPE WITH 3-1/2" OREGON STATE DEPARTMENT OF FORESTRY ALUMINUM CAP AND MAGNET, LINCOLN CS 12449, BENTON CS 8254, POLK CS 12079.

2007 LINCOLN COUNTY SURVEYOR'S OFFICE

FOUND: 2" OUTSIDE DIAMETER ALUMINUM PIPE WITH 3-12" ALUMINUM CAP, AT GRADE, MARKED "T10S R8W/R7W/ POLK CO./LINCOLN CO./BENTON CO. 1989", FROM WHICH:

- 66" DOUGLAS FIR WITH FLAT BARK BLAZE AND SCRIBING"/BT", PLUS A 1-1/4" STEEL WASHER MARKED "RS 2016", AND AN OREGON DEPARTMENT OF FORESTRY LOCATOR TAG BEARS N 17° E, 20.0" TO SIDE CENTER (CS 12449 N 19° E, 17.4').
- 18" ALDER WITH ILLEGIBLE BARK SCRIBE AND BEARING TREE TAG MARKED "CO. CORNER S60°W 19.98" BEARS N 60° E, 20.0' (= CS 12449).
- 35" FIR WITH HEALED BLAZE AND BEARING TREE TAG MARKED "N 51° E, 66.5' CO. COR" BEARS S53° W, 68.1' (CS 12449 S 51° W, 66.5').
- 2" OUTSIDE DIAMETER, 1-1/2" INSIDE DIAMETER IRON PIPE AT GRADE BEARS N 43° W, 4.38' (CS 12449 N 42°58' W, 4.38').

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Tom Hamilton

OREGON
JULY 13, 1979
THOMAS R. HAMILTON
PLS #1818

RENEWAL DATE: JUNE 30, 2009

LINCOLN COUNTY CORNER REPORT
NORTHEAST COUNTY BOUNDARY CORNER OF SECTION 12, (10-08)
GCDB 1008700565
LINCOLN COUNTY GEODETIC CONTROL STATION 50COR
SHEET 2 OF 2

- 1/2" X 4' TALL WHITE PVC PIPE BEARS SOUTHEAST, 0.3'.

NEW:

- 5/8" IRON ROD WITH 2" LINCOLN COUNTY ALUMINUM CAP AT GRADE, MARKED "50AZ 2007" BEARS N 3°21'09" E, 216.28'.
- 5/8" IRON ROD WITH YELLOW PLASTIC CAP MARKED "LINCOLN COUNTY SURVEY" BEARS N 65°20'02" W, 52.00'.
- CARSONITE POST 3' NORTH.
- WE MOVED FOUND 1/2" WHITE PVC PIPE TO 1-1/2" PIPE (GREEN), 4' NORTHWEST OF CORNER.

CONCLUSION: THE MONUMENT FOUND IS THAT SET BY STEELE. IT IS ACCEPTED AS THE COUNTY CORNER.

MEASUREMENTS WERE DONE WITH A LEICA TCA1105 TOTAL STATION, POCKET COMPASS AND STEEL TAPE. BEARINGS TO ACCESSORY MONUMENTS ARE GEODETIC, BASED UPON STARNET PROJECT 2008/10-08.PRJ AND THE MAPPING ANGLE OF -2°12'01" AT THE COUNTY CORNER.

LINCOLN COUNTY SURVEYOR'S OFFICE
880 NE 7TH ST.
NEWPORT, OREGON 97365
(541)-~~574~~-4147
265

