

**107140200**

DATE 01/19/2021TOWNSHIP 10 SOUTH, RANGE 7 WEST, WILLAMETTE MERIDIAN; SECTION 30 CORNER SOUTH 1/4  
DONATION LAND CLAIM N/A CORNER N/A**COMMON CORNER(S):**

NORTH 1/4 CORNER SECTION 31

**RECORDS (INFORMATION IN *BOLD ITALICS* IS COUNTY STAFFS' INTERPRETATION OF THE RECORD)**

BASED ON EXTENSIVE RESEARCH AND RECOVERY OF EVIDENCE, THIS OFFICE HAS DETERMINED THAT MOST GENERAL LAND OFFICE SURVEYORS IN BENTON COUNTY BEFORE 1890 MEASURED TO THE FACE OF BEARING TREES.

- [01] GENERAL LAND OFFICE (GLO) NOTES BY DENNIS HATHORN, D.S., DATED DECEMBER 5, 1856. *SET POST FROM WHICH A BURNT FIR 40" DIA BEARS S70°E, 90 LINKS (59.40 FEET); BURNT FIR 24" DIA BEARS N85°W, 80 LINKS (52.80 FEET).*
- [02] BENTON COUNTY SURVEY NO. 5732 BY WILJO E. GREEN, P.L.S., DATED MARCH, 1973. *1/4 CORNER REESTABLISHED. SET OREGON STATE BOARD OF FORESTRY 1-1/2" X 36" GALVANIZED IRON PIPE WITH 3" BRONZE CAP, 34" IN GROUND. FIR 7" DIA BEARS N8°W, 11.9 FEET; FIR 7" DIA BEARS S26°E, 8.7 FEET, RS563. FIR 2" DIA BEARS S60°W, 3.8 FEET. WHITE AND ORANGE PAINTED CEDAR POST BEARS NORTH, 1.0 FEET.*
- [03] BENTON COUNTY SURVEY NO. 5827 BY WILJO E. GREEN, P.L.S., DATED DECEMBER, 1974. *1/4 CORNER REESTABLISHED. SET OREGON STATE BOARD OF FORESTRY 1-1/2" X 36" GALVANIZED IRON PIPE WITH 3" BRONZE CAP, 34" IN GROUND. FIR 7" DIA BEARS N8°W, 11.9 FEET; FIR 7" DIA BEARS S26°E, 8.7 FEET, RS563. FIR 2" DIA BEARS S60°W, 3.8 FEET. WHITE AND ORANGE PAINTED CEDAR POST BEARS NORTH, 1.0 FEET.*
- [04] BENTON COUNTY CORNER RESTORATION NO. 575. *TRANSCRIBED FROM RECORD [03] AND MAY CONTAIN ERRORS AND/OR OMISSIONS.*

**FIRM/AGENCY:** BENTON COUNTY SURVEYOR'S OFFICE  
**ADDRESS:** 360 S.W. AVERY AVE., CORVALLIS, OR 97333; PH. 541-766-6821  
**RESEARCH BY:** DAVID L. MALONE, P.L.S.  
**DATA ENTRY BY:** SAME

BENTON COUNTY SURVEYORS OFFICE - CORNER RESTORATION


575

T 10 S, R 7 W, W. B. & M., BENTON COUNTY, OREGON

REPORTED BY Wiljo E. Green  
 TITLE Surveyor (563)  
 DATE MAR. 1973

SECTION 30

The information shown hereon was taken from  
 the referenced county survey. Date: <sup>CJL</sup> 7/25/90



● OFFICIAL CORNER FOUND

○ CORNER SET

1/4 CORNER COMMON TO SEC. 30 & 31

IS Iron Pipe Gal. W 3" Bronze Cap (CSBP)  
 DESCRIBE 1 1/2" x 36" 34" in gms

ADDITIONAL INFORMATION

Yellow Metal Location Poster on  
12" Fir S 60° W 3.8' White  
and Orange Painted Cedar Post,  
North 1.0"

See C.S. # 5827

OVER

LEGIBLE MARKS ON BEARING OBJECTS

	RS 563		
KIND	<u>Fir</u>	<u>Fir</u>	
SIZE	<u>7"</u>	<u>7"</u>	
BEARING	<u>N08° W</u>	<u>S26° E</u>	
DISTANCE	<u>11.9'</u>	<u>8.7'</u>	
BT TAG POSTED		<u>✓</u>	