

107220240

SEE COR. REST. NO. 569  
(CJL 7/17/90)

RESTORED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

Center West 1/16 corner for Section 29, Township 10 South, Range 7 West, W.M., Benton County, Oregon.

ORIGINAL (County survey in 1932)

Fir limb (missing) from which a:

- 8" Fir bears S36°20'E 1.086 ch.; now 36" Fir stump, scribe B visible.
- 36" Fir bears S70°00'W 2.386 ch.; now 47" Fir stump, face area burned away.

RESTORED

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY S29 CW 1/16 1972 RS563", 34 inches in ground in old N-S fence and in a notch chopped in an old log, and from which a:

- 14" Fir bears N76°W 13.4 ft. to face; scribed CW 1/16 S29 BT RS563.
- 13" Fir bears S55°E 3.4 ft. to face; scribed CW 1/16 S29 BT.

Set 4" x 4" x 72" white painted Cedar post 1.0 ft. SW of corner pipe. Oregon State Forestry Department metal location poster on NW BT.

Dated July 20, 1972

Restored by William M. Bonsanti under my direction.  
William M. Bonsanti

Present and witnessed by William E. Seeley  
Darryl Barker

