

107220270

JEE COR. RES. NO. 580
(CJL 7/17/90)

RESTORED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

Center North, Northwest 1/64 corner for Section 29, Township 10 South, Range 7 West, W.M., Benton County, Oregon.

ORIGINAL (County Surveyor 1932)

Fir limb (missing) from which a:

- 24" Fir bears S8°05'W 39.0 lks.; missing.
- 40" Fir bears S82°00'W 48.5 lks.; now 38" stump, scribes BT visible.

RESTORED

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY S29 CN NW 1/64 1972 RS563", 34 inches in ground, and from which a:

- 16" Fir bears S16E 92.5 ft. to face; scribed CN NW 1/64 S29 BT RS563.
- 10" Alder bears S80E 17.4 ft. to face; scribed in bark, CN NW 1/64 S29 BT.
- E-W cat road South 80.0.

Set 4" x 4" x 72" white painted Cedar post 1.0 ft. North of corner pipe. Oregon State Forestry Department metal location poster on SE BT.

Dated July 20, 1972

Restored by William E. Seeley under my direction.
William E. Seeley

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Wiljo E. Green

OREGON
JANUARY 12, 1962
WILJO E. GREEN
563

Present and witnessed by Darryl Barker