

107220300

SEE COR. REST. NO. 537  
(CJL 7/17/90).

RESTORED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

West one-sixteenth corner common to Sections 20 and 29, Township 10 South, Range 7 West, W.M., Benton County, Oregon.

ORIGINAL (By Bert Wilkes, Deputy C.S., 1923)

Cedar Post (now missing) from which a:

24" Fir bears N32E 77.4 lks.; now 30" stump in place with scribes BT visible.

RESTORED

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY W 1/16 S20 S29 1972 RS563", 33 inches in ground, in mound of rock, and from which a:

28" Fir bears S76E 84.4 ft. to face; scribed W 1/16 S29 BT RS563.

28" Fir bears N31E 76.0 ft. to face; scribed W 1/16 S20 BT.

Set 4" x 4" x 72" white painted Cedar post 1.0 ft. NW of corner pipe. Oregon State Forestry Department metal location poster on 8" Alder S33E 3.5'.

Dated July 20, 1972

Restored by William M. Bonsanti under my direction.  
William M. Bonsanti

Present and witnessed by William E. Seeley  
Darryl Barker

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Wiljo E. Green*  
OREGON  
JANUARY 12, 1962  
WILJO E. GREEN  
563