

~~4" long 8" in the ground over which set a Sandstone 10" X 8" X 8", 8" in ground from which a white oak 9" in dia. bears N 42 15 W 71 lks. dist. marked T 7 S R 5 W C 68 B T.~~

~~a white oak 12" in dia bears S 70° 45' W. 103 lks. dist marked T 7 S R 5 W C 68. B T.~~

~~Witnesses
J. A. Jauned
J. B. Window.
Hugh Hayes
Reed~~

~~Geo. P. Van Orsdel
County Surveyor
Polk Co.~~

190
195

The cor. of sections 2, 3, 10 & 11 in Tp 10 S, R 7 W of the Willamette meridian in the County of Polk and the State of Oregon.

I found two of the original bearing trees still standing but the trees have been chopped so much looking for marks that the marks are nearly destroyed. The other trees have been cut but found marks on stumps of same.

I have reestablished the corner by setting a stake 4" X 4" X 4 ft long firmly in ground from which a fir 26" in dia. bears S 38° 15' E. 86 lks dist. marked T 10 S R 7 W S 11 B T.
a fir 30" in dia. bears S 1° 30' W. 68 lks dist. marked T 10 S R 7 W S 10 B T.
a fir 30" in dia. bears N 84° E 121 lks

SEE COR. REST
No. 449
CC-711 (90)

BENTON COUNTY SURVEYORS OFFICE - CORNER RESTORATION

449


T 10 S, R 7 W, W. B. & M., BENTON COUNTY, OREGON

SECTION 2

REPORTED BY Jno. P. Van Orsdal

TITLE Polk Co. Surveyor

DATE 1900.-1902



● OFFICIAL CORNER FOUND

○ CORNER SET

SEC. CORNER COMMON TO SEC. 2, 3, 10 & 11

IS 4" x 4" x 48"

DESCRIBE

ADDITIONAL INFORMATION

Found original bearing trees but trees
were chopped so much by people looking
for marks that makes were nearly destroyed.

Polk County Records

LEGIBLE MARKS ON BEARING OBJECTS

	T10SR7W S11 B.T.	T10SR7W S10 B.T.	
KIND	Fir	Fir	Fir
SIZE	26"	30"	30"
BEARING	S38°15'E	S1°30'W	N84°E
DISTANCE	86 lks	68 lks	121 lks
BT TAG POSTED			

OVER

Recorded $\frac{1}{4}$ Sec. corner on the West of Sec 7, T10S R6W
 from Benton $\frac{1}{4}$ " Pipe from which
 B. Surveys SEE COR. REST. No. 332 (CJL 7/11/90)
 W.W. Larson Oak 4" in dia. bears $N72^{\circ}40'E$. 074 chs.
 " 6" " " $S2^{\circ}40'E$. 289 "

$\frac{1}{4}$ Sec cor on the west of Sec 12, T10S R7W
 Peavy point from which
 1.1 Fir 8" in dia. bears $S3^{\circ}15'E$. 229 chains
 " 12" " " $N68^{\circ}W$. 15 "

W.W. Larson S.W. corner of Sec 2, T10S R7W
 F.E. Price Set $1\frac{1}{2}$ " Pipe SEE COR. REST. NO. 452 (CJL 7/11/90)

1.1 $\frac{1}{4}$ Sec cor. on the south line of Sec 2, T10S R7W
 SEE COR. REST. NO. 451 (CJL 7/11/90)
 Set $1\frac{1}{2}$ " Pipe N. of fence

W.W. Larson $\frac{1}{4}$ Sec cor on north line of Sec. 6, T. 10S R6W
 Dep. C.S. Set a $1\frac{1}{4}$ " rod from which
 Oct 6, 1934
 Glen Kerber Wit. a Fir 24" in dia. bears $S21^{\circ}W$. 350 chains
 SEE COR. REST. NO. 326 (CJL 7/11/90).
 " Stump $N47^{\circ}W$. 82 "

C.S. #270, Corner to Secs. 19, 20, 29 & 30, T. 11 S. R. 5 W

Set stone, 8' N. of ditch

Alder 22" in dia. bears	N. 22° 30' E.	.631	chs.	
" 10" " " "	N 53° 30' E.	6.02	"	std. 1; (not measured)
" 20" " " "	S. 53° E.	.325	"	
" 12" " " "	Oak 20" N. 48 1/2° W. 793	.35	"	
" 10" " " "	S. 71° W	3.90	"	did not measure
" 10" " " "	N 62° 30' W.	1.47	"	

Witnesses as above March 29, 1918.

C.S. 222 1/4 sec. cor. between Secs. 31 & 36 T. 14 S. R. 5 W.

continued.

Set a 1/2" pipe under a stone 4" x 5" x 9"

H. h 10" in dia. bears S. 62 1/2° E. .23 chs. std.

Balm 30" " " " N. 10° W. .35 " "

Witnesses Frank Rickards, T. Pinnell, W.S. Barnes et al. May 13, 1918.

1/4 sec. cor. on south of Sec. 31 T. 14 S. R. 4 W.

Set 1/2" galv. pipe 28" long set from 2 ash stumps.

Maple 30" in dia. bears S. 49 3/4° W. .683 chs.

" 40" " " " N. 83 1/4° W. .813 "

Witnesses T. Pinnell, Green Favor June 11, 1918.

Corner to Secs. 31, 32, 5 & 6 Tps. 14 & 15 S. R. 4 W.

Set stone 6" x 7" x 20" W down check Fir & S.E. ash almost checks.

Maple 24" in dia. bears N. 29° E. .406 chs.

Ash 10" " " " S. 16° E. .25 " std.

Fir 8" " " " S 39 3/4° W. .630 "

Maple 40" " " " N. 34° W. .742 "

Witness T. Pinnell June 10, 1918.

C.S. #213 1/4 sec. corner on the south line of sec. 36 T. 13 S. R. 6 W.

Set an oak stake 3" x 24"

Fir 15" in dia. bears N. 1° 10' E. .547 chs.

" 20" " " " N 47° 30' W. 156 "

Witness Frank Burnap July 8, 1918.

Survey for Frank Price in Polk Co.

Witnesses Frank Price

& S.M. Wood

1/4 sec. corner between Secs. 2 & 11 T. 10 S. R. 7 W.

Set 1/2" pipe. Replaced fir stake set by toll. o. C.S.

July 15, 1918.

Corner to Secs. 2, 3, 10 & 12, T. 10 S. R. 7 W

Set 1 1/2" pipe

Hemlock 8" in dia. bears S. 15° E. .06 chs. std.

Fir 10" " " " S. 5° E. .66 " "

Stump of " 12" " " " N. 4° W. 1625 " "

July 15, 1918.

1/4 sec. cor. bet. Secs. 2 & 11 T. 10 S. R. 7 W.

Stone 20" x 14" x 5" set by Polk Co. Surveyor.

July 15, 1918.

Corner to sections 2, 3, 10, and 12, Twp. 10 S., R. 7 W.

452

Reestablishment by W. C. Galloway

July 15, 1918

Set 1½" pipe

Hemlock 8" in diam bears S 15° E

.56 chains(standing)

Fir 10" in diam bears S 5° E

.66 chains(standing)

Stump of Fir 12" in diam bears N 4° W

1.625 chains(standing)

Witnesses Frank Price and S. M. Wood.

107500600

GOVERNMENT CORNER RESTORATION

T 10 S R 7 W

Polk County, Oregon

Nov, 10, 1967

38

At the corner common to sections 2-3-10-11, I find the following evidence of the Bearing Trees marked in 1900-1902 by VanOrsdale (Book B Page 51):

40" (26") FIR STUMP	S 38°15'E	56.8 ft	Fnd "BT"
40" (30") FIR STUMP	S 1°30'W	44.9 ft	Fnd scribes

At the corner I found set a 1 1/2" iron pipe (Book "C" page 124) in which I set a Polk County Brass Cap.

From the corner I marked the following new bearing trees:

10" FIR	S 37° E	41.4 ft	Mkd S 11 BT
8" FIR	S 45°W	30.4 ft	Mkd S 10 BT
5" WILD CHERRY	N 73°E	5.8 ft	Mkd S 2 BT

WITNESS: PHIL SHARTZER

REGISTERED OREGON LAND SURVEYOR

C. Ralph Blanchard

JULY 14, 1967
C. RALPH BLANCHARD
786

GOVERNMENT CORNER RESTORATION

T 10 S R 7 W

Polk County, Oregon

Nov 10, 1967

At the 1/4 corner between sections 2 & 11 I find the following evidence of the bearing trees marked VanOrsdale in 1900-1902 (Book B page 514):

40" (30") FIR STUMP	N 73°45'W	19.8 ft	Badly charred
30" (18") FIR STUMP	S 44°15'W	37.0 ft	" "

At the corner I found set a 1 1/2" iron pipe (Book C page 124) in which I set a Polk County Brass Cap

From the corner I marked the following new bearing trees:

20" ALDER	N 56° 32' W	42.4 ft	Mkd 1/4 S BT
8" FIR	S 4° 26' W	61.1 ft	Mkd 1/4 S BT

WITNESS: PHIL SHARTZER

REGISTERED OREGON LAND SURVEYOR

C. Ralph Blanchard

JULY 14, 1967
C. RALPH BLANCHARD
786

GOVERNMENT CORNER RESTORATION

T. 8 S. R. 6 W. WM.

SEE COR. REST.

No. 454

(CJL 7/11/90)

②

SEE COR. REST.

No. 453

(CJL 7/11/90)

③

BENTON COUNTY SURVEYORS OFFICE - CORNER RESTORATION

454


T. 10 S, R. 7 W, W. B. & M., BENTON COUNTY, OREGON

REPORTED BY C. Ralph Blanchard

SECTION 2

TITLE Land surveyor

DATE Nov. 10, 1967



● OFFICIAL CORNER FOUND

○ CORNER SET

Sec. CORNER COMMON TO SEC. 2, 3, 11 & 10
 IS 1 1/2" iron pipe with Polk Co. Brass cap

DESCRIBE

ADDITIONAL INFORMATION

Polk County records

(26")

FND: 40" FIR STUMP S38°15'E 56.8 FT. FND. "BT"

FND: 40" (30") FIR STUMP S1°30'W 44.9 FT. FND. SCRIBES

(CJL 7/11/90)

LEGIBLE MARKS ON BEARING OBJECTS

	S11	S10	S2
	B.T.	B.T.	B.T.
KIND	Fir	Fir	wild cherry
SIZE	10"	8"	5"
BEARING	S37°E	S45°W	N73°E
DISTANCE	41.4 ft	30.4 ft	5.8 ft
BT TAG POSTED			

OVER