

107660520

BENTON COUNTY SURVEYORS OFFICE - CORNER RESTORATION

3274


T. 10 S, R. 7 W, W. B. & M., BENTON COUNTY, OREGON

SECTION 12

REPORTED BY Theodore Langton

TITLE Reg Land Surveyor

DATE June 13, 1984



● OFFICIAL CORNER FOUND

○ CORNER SET

1/16 CORNER COMMON TO SEC. 12
IS 5/8" x 30" rebar

DESCRIBE

ADDITIONAL INFORMATION

yellow cap on rebar stamped
"Northstar PLS 1823", white
fiberglass fence post along-
side.

OVER

LEGIBLE MARKS ON BEARING OBJECTS

	Set	Set		
	SE 1/16 S12 BT	SE 1/16 S12 BT		
KIND	D-fir	oak		
SIZE	16"	20"		
BEARING	N67°W	N30°E		
DISTANCE	14.46'	24.64'		
BT TAG POSTED				

