


107660560

BENTON COUNTY SURVEYORS OFFICE - CORNER RESTORATION

3279

10 S, R 7 W, W. B. & M., BENTON COUNTY, OREGON
SECTION 12

REPORTED BY Theodore Langston
TITLE Reg. Land Surveyor
DATE June 13, 1984



● OFFICIAL CORNER FOUND
○ CORNER SET

1/16 CORNER COMMON TO SEC. 12
IS 5/8" x 30" rebar
DESCRIBE

ADDITIONAL INFORMATION

yellow cap on rebar stamped
"Northstar PLS 1823" white
fiberglass fence post along-
side.

OVER

LEGIBLE MARKS ON BEARING OBJECTS

	Set	Set		
	NE 1/16 S 1/2 BT	NE 1/16 S 1/2 BT		
KIND	ash.	D-Fir		
SIZE	16"	4"		
BEARING	S 64° E	S 83° W		
DISTANCE	30.16'	10.77'		
BT TAG POSTED				

REGISTERED
PROFESSIONAL
LAND SURVEYOR
Theodore Langston
THEODORE LANGSTON
1983