

116260100

3509

BENTON COUNTY SURVEYORS OFFICE - CORNER RESTORATION


T. 11 S. R. 6 W. W. B. & M., BENTON COUNTY, OREGON

SECTION 32

REPORTED BY Jim S. PETERSON

TITLE LAND SURVEYOR

DATE 2-3-88



● OFFICIAL CORNER FOUND

○ CORNER SET

1/16 CORNER COMMON TO SEC. 32 & 5  
IS 1" AXLE

DESCRIBE

ADDITIONAL INFORMATION

GALLOWAY HARD COPY 11-6-00011 SHOWS  
 A "CAR AXLE" FOR THIS CORNER. A  
 CHECK OF THE FIELD NOTES SHOWS THE  
 CORNER WAS SET BY MARTIN REYERLEIN  
 ON 5-18-51.

OVER

LEGIBLE MARKS ON BEARING OBJECTS

NEW BT'S

	E 1/16 S 35 BT	E 1/16 S 32 BT		
KIND	FIR	FIR		
SIZE	12"	10"		
BEARING	SOUTH	N 62° W		
DISTANCE	35 1/2 FT	16 1/2 FT		
BT TAG POSTED	/	/		

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

OREGON  
JULY 21, 1976  
JIM S. PETERSON  
1034