

**116838030**

DATE 03/03/2022TOWNSHIP 11 SOUTH, RANGE 6 WEST, WILLAMETTE MERIDIAN; SECTION 5 CORNER N/A  
DONATION LAND CLAIM JOB S. HAWORTH NO. 38 CORNER SOUTHWEST**COMMON CORNER(S):**

INTERIOR CORNER OF THE REUBEN F. BURGET DONATION LAND CLAIM (DLC) NO. 57

**RECORDS (INFORMATION IN *BOLD ITALICS* IS COUNTY STAFFS' INTERPRETATION OF THE RECORD)**

BASED ON EXTENSIVE RESEARCH AND RECOVERY OF EVIDENCE, THIS OFFICE HAS DETERMINED THAT MOST GENERAL LAND OFFICE SURVEYORS IN BENTON COUNTY BEFORE 1890 MEASURED TO THE FACE OF BEARING TREES.

- [01] GENERAL LAND OFFICE (GLO) NOTES OF THE JOB S. HAWORTH DONATION LAND CLAIM (DLC) NO. 38 BY DENNIS HATHORN, D.S., DATED DECEMBER 8, 1854. *SET POST FROM WHICH AN OAK 30" DIA BEARS S15°E, 369 LINKS (243.54 FEET); OAK 20" DIA BEARS S42°W, 340 LINKS (224.40 FEET).*
- [02] GENERAL LAND OFFICE (GLO) NOTES OF THE REUBEN F. BURGET DONATION LAND CLAIM (DLC) NO. 57 BY DENNIS HATHORN, D.S., DATED MARCH 24, 1855. *SOUTHWEST CORNER OF CLAIM 38 FROM WHICH AN OAK 20" DIA BEARS N72°W, 300 LINKS (198.00 FEET); OAK 9" DIA BEARS S84°W, 229 LINKS (151.14 FEET).*
- [03] BENTON COUNTY SURVEY NO. 468 (OLD NO. 214) FIELD NOTES (FIELD BOOK 17, PAGE 58) BY BURT WILKES, D.C.S., DATED SEPTEMBER 15, 1914. *REESTABLISH 3/4" X 18" BOLT. SOUTHEAST TREE OK. SOUTHWEST STUMP NEARLY GONE. MARK OAK 10" DIA BEARS S27°W, 2.522 CHAINS (166.45 FEET).*
- [04] BENTON COUNTY CORNER RESTORATION BOOK NO. 1, PAGE 85, BY BURT WILKES, D.C.S., DATED SEPTEMBER 30, 1914. *SET 3/4" X 18" BOLT FROM WHICH OAK 30" DIA (GLO BT) BEARS S15°E, 3.69 CHAINS (243.54 FEET), STANDING; OAK 20" DIA (GLO BT) BEARS S42°W, 3.40 CHAINS (224.40 FEET), STUMP ROTTEN; OAK 10" DIA (CSBT) BEARS S27°W, 2.522 CHAINS (166.45 FEET), NEW.*
- [05] BENTON COUNTY CORNER RESTORATION NO. 398. *TRANSCRIBED FROM RECORD [04] AND MAY CONTAIN ERRORS AND/OR OMISSIONS.*
- [06] BENTON COUNTY CORNER RESTORATION NO. 3259. *TRANSCRIBED FROM RECORD [04] AND MAY CONTAIN ERRORS AND/OR OMISSIONS.*
- [07] BENTON COUNTY SURVEY NO. 468 MAP (OLD NO. 214) BY BURT WILKES, D.C.S., DATED SEPTEMBER 30, 1914. *SET 3/4" X 18" BOLT. OAK 30" DIA (GLO BT) BEARS S15°E, 3.69 CHAINS (243.54 FEET); OAK 20" DIA (GLO BT) BEARS S42°W, 3.40 CHAINS (224.40 FEET), STUMP; MARK OAK 10" DIA (CSBT) BEARS S27°W, 2.522 CHAINS (166.45 FEET).*
- [08] BENTON COUNTY MAP NO. 10&11-6-00015 BY BURT WILKES, D.C.S., DATED SEPTEMBER 30, 1914. *SET 3/4" X 18" BOLT. OAK 30" DIA (GLO BT) BEARS S15°E, 3.69 CHAINS (243.54 FEET); OAK 20" DIA (GLO BT) BEARS S42°W, 3.40 CHAINS (224.40 FEET), STUMP; MARK OAK 10" DIA (CSBT) BEARS S27°W, 2.522 CHAINS (166.45 FEET). BOLT CROSSED OUT AND 1-1/4" PIPE ADDED BY MLB, 1953.*
- [09] BENTON COUNTY SURVEY NO. 2477 LOOSE LEAF NOTES BY MARTIN L. BEYERLEIN, D.C.S., DATED APRIL, 1953. *SET 1-1/4" PIPE FROM ORIGINAL OAK 30" BEARING TREE, 15" FROM CENTERLINE. THIS PIPE CHANGE SOUTH 0.013 CHAINS (0.86 FEET) AND WEST 0.024 CHAINS (1.58 FEET) TO FIT PLAT AND BOTH BEARING TREES. PIPE NOW 0.062 CHAINS (4.09 FEET) NORTH AND 0.084 CHAINS (5.54 FEET) EAST OF FENCE CORNER.*
- [10] BENTON COUNTY SURVEY NO. 2477 BY CURTIS C. HANSON, C.S., DATED APRIL 30, 1953. *SET 1-1/4" PIPE.*
- [11] BENTON COUNTY SURVEY NO. 4681 BY RICHARD W. FAIL, P.L.S., DATED OCTOBER 24, 1968. *FOUND 1-1/4" PIPE.*
- [12] BENTON COUNTY SURVEY NO. 4798 BY RICHARD W. FAIL, P.L.S., DATED AUGUST 23, 1969. *FOUND 1-1/4" PIPE.*
- [13] BENTON COUNTY SURVEY NO. 8336 BY THEODORE JAMES LANGTON, P.L.S., DATED OCTOBER 4, 1989. *FOUND 1-1/4" INSIDE DIAMETER IRON PIPE WITH 5/8" ROD INSIDE PIPE, LIES N64°E, 6.5 FEET FROM FENCE CORNER.*

**FIRM/AGENCY:** BENTON COUNTY SURVEYOR'S OFFICE  
**ADDRESS:** 360 S.W. AVERY AVE., CORVALLIS, OR 97333; PH. 541-766-6821  
**RESEARCH BY:** DAVID L. MALONE, P.L.S.  
**DATA ENTRY BY:** SAME

C.S. #214  
SEPT. 15 1830-1914



S.W. Corner Job. S. Hayworth D.L.C. #38 - T. 10 S., R. 6 W.  
Set  $\frac{3}{4}$ " x 15" bolt. From which  
Oak 30 S. 15° E. 3.69 Standing  
" 20 S. 42° W. 3.40 Stump (rotten)  
" 10 S. 27° W. 2.522 New.

S.E. Corner Job. S. Hayworth D.L.C. N. 38 10-11-6

Set stone 14x10x8" underneath stone 15x8x6"

Oak 9" S. 82° W. 2.20 standing not 2-29

" 20" N. 70 $\frac{1}{2}$ ° W. 3.00 Stump

" 15" N. 3° W. .530 New

" 5" N. 80 $\frac{1}{2}$ ° W. .065 "

N.E. Corner of Cl. N. 38. Job. S. Hayworth - 10-11-6

Set 1 $\frac{1}{2}$ " x 48" Mower Axle. from which

Oak 20" S. 14° W. 3.14 Stump

Mark oak 7. S. 50 $\frac{3}{4}$ ° E. 9.19 New.

" " 10 S. 27° W. 2.022 "

S.E. Cor. Isaac King D.L.C. N. 39. - T. 10 S., R. 6 W.

Set stone 16" x 12" x 7" - from which

Oak 20" <sup>(S. 72° E)</sup> S. 72 $\frac{3}{4}$ ° E. 1.99 standing

" 12" <sup>(N. 20° W)</sup> N. 17 $\frac{3}{4}$ ° W. 4.54 "

The N.E. Cor. Cl. 38 bears S. 89° 46' W. 1.75

S.W. Corner of Isaac King Cl. #39 - 10-6

Set 1 $\frac{1}{4}$ " x 30" =  $\frac{1}{2}$  Buggy Axle -

Oak 30 - S. <sup>5°</sup> ~~27°~~ E. 63 standing

" 18 N. 65° E. 1.21 "

N.E. Corner R.F. Burgett Cl. 57 = N.W. Cor. Geo. Landerkin Cl. #58 - 11-6

C.S. #216

Oct. 22-24-1914

N.W. Corner <sup>L.E.</sup> Penland D.L.C. #63 - 12-13 S. 6 W.

Set  $\frac{3}{8}$ " x 16" spoke of master wheel of Binder

Oak 24" S. 75° E. 2.96 - Not 1.76

Other Tree gone.

Witness - Millard Brown.

N.E. corner thos H. Litville Cl. #66 - 12-6

Set.

Oak 12" S. 69° W. 5.79 Stump

" " S. 52° E. 2.7 "

Nowitnesses

Witnesses Jos Casarone, Wiley Plumhart, Henry Plumhart, Clair Wilkes

S. W. corner Job S. Hayworth DLC 38, Twp. 10 and 11 S R 6 W

398

1069

Reestablishment by W. C. Galloway

September 15, 1914

Set  $\frac{3}{4}$ " x 18" bolt

Oak 30" in diam bears S 15°E

3.69 chains(standing)

Oak 20" in diam bears S 42°W

3.40 chains(rottenstm)

Oak 10" in diam bears S 27° W

2.522 chains

S. W. Corner of Job S. Hayworth D.LC. 38 in 11-6

Reestablishment by E. Wilkes

3259

Set 3/4" x 18" bolt

Oak 30"	S. 15° E.	3.69 chs. (std.)
Oak 20"	S. 42° W.	3.40 chs. Stump
Oak 10"	S. 27° W.	2.522chs. New

1068

Witnesses James Cosgrove, Wiley Plunkett, Henry Plunkett, Clair Wilkes