

BENTON COUNTY CORNER HISTORY FORM, PAGE 1 OF 1,

117200500H

DATE 04/15/2021

TOWNSHIP 11 SOUTH, RANGE 7 WEST, WILLAMETTE MERIDIAN; SECTION 7 CORNER SOUTHEAST DONATION LAND CLAIM N/A CORNER N/A

COMMON CORNER(S):

SOUTHWEST CORNER SECTION 8
NORTHWEST CORNER SECTION 17
NORTHEAST CORNER SECTION 18

RECORDS (INFORMATION IN BOLD ITALICS IS COUNTY STAFFS' INTERPRETATION OF THE RECORD)

BASED ON EXTENSIVE RESEARCH AND RECOVERY OF EVIDENCE, THIS OFFICE HAS DETERMINED THAT MOST GENERAL LAND OFFICE SURVEYORS IN BENTON COUNTY BEFORE 1890 MEASURED TO THE FACE OF BEARING TREES.

- [01] GENERAL LAND OFFICE (GLO) NOTES BY DENNIS HATHORN, D.S., DATED JULY 7, 1856. SET POST FROM WHICH A BURNT CEDAR 15" DIA BEARS N50°E, 225 LINKS (148.50 FEET); FIR 30" DIA BEARS N15°W, 464 LINKS (306.24 FEET); FIR 30" DIA BEARS S50°E, 243 LINKS (160.38 FEET); FIR 24" DIA BEARS S25°W, 366 LINKS (241.56 FEET).
- [02] PAGE 79 OF THE RECORD BOOK OF SURVEYS BY ANDREW L. PORTER, C.S., NO DATE GIVEN. SET NEW POST, TREES IN GOOD ORDER.
- [03] SURVEY NO. 54, PAGE 92 OF THE RECORD BOOK OF SURVEYS BY ANDREW L. PORTER, C.S., DATED JUNE, 1890. CORNER NOT DESCRIBED.
- [04] BENTON COUNTY SURVEY NO. 195 FIELD NOTES (FIELD BOOK 7, PAGE 32) BY J. A. GANONG, D.C.S., DATED DECEMBER 5, 1910. CORNER NOT DESCRIBED.
- [05] BENTON COUNTY SURVEY NO. 195 MAP BY UNKNOWN DRAFTSMAN, NO DATE GIVEN. 4"X4" STAKE.
- [06] BENTON COUNTY SURVEY NO. 441 (OLD NO. 207) FIELD NOTES (FIELD BOOK 17, PAGE 12) BY BURT WILKES, D.C.S., DATED APRIL 17, 1914. CORNER NOT DESCRIBED.
- [07] BENTON COUNTY SURVEY NO. 441 MAP BY BURT WILKES, D.C.S., DATED APRIL 27, 1914. CORNER NOT DESCRIBED.
- [08] BENTON COUNTY MAP NO. 11-7-00004 BY BURT WILKES, D.C.S., DATED APRIL 27, 1914. CORNER NOT DESCRIBED.
- [09] RESTORED CORNER FOR STATE OF OREGON DEPARTMENT OF FORESTRY BY WILJO E. GREEN, P.L.S., DATED AUGUST 14, 1978. DOWN BURNT CEDAR 20" DIA (GLO BT) BEARS N44°40'E, 225 LINKS (148.50 FEET), ROOTS AROUND BASE, NO SCRIBE VISIBLE; ROTTED FIR STUMP BEARS N15°W, 464 LINKS (306.24 FEET), NO SCRIBE VISIBLE. SET 1-1/2" X 36" GALVANIZED IRON PIPE WITH 3" BRONZE CAP MARKED "OREGON STATE BOARD OF FORESTRY T11S R7W S7 S8 S17 S18 1978 RS563", 33" IN GROUND, FROM WHICH A FIR 16" DIA BEARS N77°E, 13.5 FEET TO FACE, SCRIBED "T11S R7W S8 BT"; FIR 19" DIA BEARS S71°W, 28.5 FEET TO FACE, SCRIBED "S18 T11S R7W RS 563 BT"; FIR 37" DIA BEARS S6°W, 23.9 FEET TO FACE, SCRIBED "S18 T11S R7W BT"; ALDER 7" DIA BEARS N5-1/2°W, 26.9 FEET TO FACE, SCRIBED IN BARK "T11S R7W S7 BT". OLD FENCE POST AND STARKERS WHITE PAINTED CEDAR POST BEARS N71-1/2°W, 8.2 FEET. SET 4" X 4" X 72" WHITE PAINTED CEDAR POST 1.5 FEET NORTHEAST OF CORNER PIPE.
- [10] BENTON COUNTY CORNER RESTORATION NO. 1010. TRANSCRIBED FROM RECORD [09] AND MAY CONTAIN ERRORS AND/OR OMISSIONS.
- [11] BENTON COUNTY SURVEY NO. 6784 BY WILJO E. GREEN, P.L.S., DATED AUGUST, 1978. SECTION CORNER FOUND. OREGON STATE BOARD OF FORESTRY 1-1/2" GALVANIZED IRON PIPE WITH 3" BRONZE CAP, 4 BEARING TREES.

FIRM/AGENCY: BENTON COUNTY SURVEYOR'S OFFICE

ADDRESS: 360 s.w. avery ave., corvallis, or 97333; ph. 541-766-6821

RESEARCH BY: DAVID L. MALONE, P.L.S.

DATA ENTRY BY: SAME

Doive . SEE COR. REST. 140. 1010 (CJL 7/16/00)

RESTORED CORNER FOR STATE OF OREGON - DEPARTMENT OF FORESTRY

Section corner common to Sections 7, 8, 17 and 18, Township 11 South, Range 7 West, W.M., Benton County, Oregon.

ORIGINAL

Post (now missing) from which a:

15" burnt cedar bears N50°E 225 1ks.; now down 20" burnt cedar N44°40'E Roots around base, no scribe visible.

30" Fir bears N15W 464 lks.; now rotted stump in place, no scribe visible.

30" Fir bears S50°E 243 lks.; now missing.

24" Fir bears S25°W 366 lks.; now missing.

Branch 3 1ks. wide, South 7.45 chs. (now 504.5') course, East.

Branch 2 1ks. wide North 11.70 chs. (now 768.2') course East.

RESTORED

Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T 11 S R 7 W \$7, \$8, \$17, \$18 1978 R\$563", 33 inches in ground, and from which a:

16" Fir bears N77 $^{\rm O}$ E 13.5 ft. to face; scribed T11S R7W $^{\rm O}$ S8 BT. 19" Fir bears S71 $^{\rm O}$ W 28.5 ft. to face; scribed S18 T11s R7W RS 563 BT. 37" Fir bears S06 $^{\rm O}$ W 23.9 ft. to face; scribed S18 T11S R7W BT.

7" Alder bears NO5½°W 26.9 ft. to face; scribed in bark T11S R7W S7 BT.

Old fence post & Starkers white painted cedar post N71 $\frac{1}{2}^{O}W$ 8.2'.

Set 4" x 4" x 72" white painted Cedar post 1.5' ft. NE of corner pipe. Oregon State Forestry Department metal location poster on 19" Fir BT 571°W 28.5'.

District Engineer

Dated August 14, 1978.

Restored by

under my direction.

REGISTERED PROFESSIONAL

Present and witnessed by W. M. Bonsanti and D. R. Wiger

Mark E. Steele,

OREGON

SURVEYOR

seen

QUARY 12, 1962 MILIO E. GREEN

RESTORED CORNER FOR STATE OF OREGON - DEPARTMENT OF FORESTRY

Section corner common to Sections 7, 8, 17 and 18, Township 11 South, Range 7 West, W.M., Benton County, Oregon.

ORIGINAL

Post (now missing) from which a:

15" burnt cedar bears N50°E 225 lks.; now down 20" burnt cedar N44°40'E Roots around base, no scribe visible.

30" Fir bears N15W 464 lks.; now rotted stump in place, no scribe visible.

30" Fir bears S50°E 243 lks.; now missing.

24" Fir bears S25°W 366 lks.; now missing.

Branch 3 lks. wide, South 7.45 chs. (now 504.5') course, East. Branch 2 lks. wide North 11.70 chs. (now 768.2') course East.

RESTORED

Set $1\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T 11 S R 7 W S7, S8, S17, S18 1978 RS563", 33 inches in ground, and from which a:

16" Fir bears N77°E 13.5 ft. to face; scribed T11S R7W S8 BT.

19" Fir bears S710W 28.5 ft. to face; scribed S18 Tlls R7W RS 563 BT.

37" Fir bears SO6°W 23.9 ft. to face; scribed S18 T11S R7W BT.

7" Alder bears NO5½ W 26.9 ft. to face; scribed in bark T11S R7W S7 BT.

Old fence post & Starkers white painted cedar post N71½°W 8.2'.

Set 4" x 4" x 72" white painted Cedar post 1.5' ft. NE of corner pipe. Oregon State Forestry Department metal location poster on 19" Fir BT $571^{\circ}W$ 28.5'.

Dated August 14, 1978.

1010

11

Restored by Mick E. Steele, District Engineer

under my direction.

Present and witnessed by W. M. Bonsanti and D. R. Wiger

REGISTERED PROFESSIONAL LAND, SURVEYOR

> JANUARY 12, 1962 WILLO E GREEN