

C. S. 98

117300160

SEE COR. REST. No. 1149
(C.L.L. 7/16/90).

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

North One-sixteenth corner common to Sections
32 and 33, T11S, R7W, W.M., Benton County,
Oregon.

ORIGINAL by F. M. Wilkes Dec. 31, 1908

Stone 3" x 6" x 12" (found in place) from which a:

20" dead fir bears N66°E 32.7 lks.; now 20" snag, scribes CS 1/16 31 BT visible.
8" dead fir bears N43 3/4°W 19.8 lks.; now 40" decayed snag, no scribes.

RESTORED

Marked X on top of stone from which a:

14" Fir bears N2 1/2°W 5.0 ft.; scribed N 1/16 S32 BT.
22" Fir bears S47 1/2°E 16.6 ft.; scribed N 1/16 S33 BT RE2311.

Oregon State Board of Forestry metal location poster on 14" BT.
Set 4 x 4 x 72" white painted Cedar post 2 feet Southwest of stone.

Dated August 24, 1960

Restored by *Billy E. Davis* under my direction.
Billy E. Davis, Transitman



Present and witnessed by D. Steenson
R. Penniman