

117300200

DATE 02/25/2020TOWNSHIP 11 SOUTH, RANGE 7 WEST, WILLAMETTE MERIDIAN; SECTION 28 CORNER SOUTHWEST
DONATION LAND CLAIM N/A CORNER N/A**COMMON CORNER(S):**SOUTHEAST CORNER SECTION 29
NORTHEAST CORNER SECTION 32
NORTHWEST CORNER SECTION 33**RECORDS (INFORMATION IN *BOLD ITALICS* IS COUNTY STAFFS' INTERPRETATION OF THE RECORD)**

BASED ON EXTENSIVE RESEARCH AND RECOVERY OF EVIDENCE, THIS OFFICE HAS DETERMINED THAT MOST GENERAL LAND OFFICE SURVEYORS IN BENTON COUNTY BEFORE 1890 MEASURED TO THE FACE OF BEARING TREES.

- [01] GENERAL LAND OFFICE (GLO) NOTES BY DENNIS HATHORN, D.S., DATED JULY 7, 1856. *SET POST FROM WHICH A BURNT CEDAR 36" DIA BEARS N35°W, 78 LINKS (51.48 FEET); BURNT CEDAR 12" DIA BEARS N52°E, 66 LINKS (43.56 FEET); BURNT CEDAR 20" DIA BEARS S40°W, 35 LINKS (23.10 FEET); BURNT CEDAR 30" DIA BEARS S4°E, 24 LINKS (15.84 FEET).*
- [02] BENTON COUNTY SURVEY NO. 98 (OLD NO. 31) FIELD NOTES (FIELD BOOK 2, PAGE 50) BY F. MARION WILKES, C.S., DATED DECEMBER 31, 1908. *FOUND OLD STAKE ROTTED. FOUND OLD TREES DOWN. SET THIMBLE AND BOXING OF 2-1/4" WAGON. DEAD FIR 44" DIA BEARS N46°E, 56.1 FEET; DEAD FIR 42" DIA BEARS S68°25'E, 41.1 FEET; DEAD FIR 24" DIA BEARS S42°W, 24.1 FEET; DEAD FIR 42" DIA BEARS N76°20'W, 42.0 FEET.*
- [03] BENTON COUNTY CORNER RESTORATION BOOK NO. 1, PAGE 3 BY F. MARION WILKES, C.S., NO DATE GIVEN. *SET THIMBLE AND BOXING OF 2-1/2" WAGON. OLD TREES DOWN, NO LIVE TREES. DEAD FIR 44" DIA BEARS N46°E, 56.1 FEET; DEAD FIR 42" DIA BEARS S68°25'E, 41.1 FEET; DEAD FIR 24" DIA BEARS S42°W, 24.1 FEET; DEAD FIR 42" DIA BEARS N76°20'W, 42.0 FEET.*
- [04] BENTON COUNTY CORNER RESTORATION NO. 1113. *TRANSCRIBED FROM RECORD [03] AND MAY CONTAIN ERRORS AND/OR OMISSIONS.*
- [05] BENTON COUNTY SURVEY NO. 3781 BY LOUIS W. AMORT, P.E., DATED JUNE 14, 1960. *FOUND 2-1/2" WAGON THIMBLE AND BOXING FROM WHICH A BADLY DECAYED FIR SNAG (CSBT) BEARS N46°E, 56.1 FEET, NO SCRIBES REMAINING; BADLY DECAYED FIR STUMP (CSBT) BEARS S68°25'E, 41.1 FEET; ROTTED FIR STUMP (CSBT) BEARS S42°W, 24.1 FEET, NO SCRIBES; REMAINS OF FIR STUMP (CSBT) BEARS N76°20'W, 42.0 FEET. SET 1-1/2" X 36" GALVANIZED IRON PIPE WITH 3" BRONZE CAP MARKED "OREGON STATE BOARD OF FORESTRY T11S R7W S29 S28 S32 S33 1960 RE2311", 30" IN GROUND IN PLACE OF WAGON AXLE, FROM WHICH A FIR 4" DIA BEARS S5-1/2°W, 3.0 FEET, SCRIBED "T11S R7W S32 BT"; FIR 6" DIA BEARS S40°E, 118.0 FEET, SCRIBED "T11S R7W S33 BT"; FIR 4" DIA BEARS N31°E, 52.4 FEET, SCRIBED "T11S R7W S28 BT"; FIR 5" DIA BEARS N66-1/2°E, 49.8 FEET, SCRIBED "T11S R7W S29 BT RE2311". METAL LOCATION POSTER ON 4" BT BEARS S5-1/2°W. SET 4" X 4" X 72" WHITE PAINTED CEDAR POST 1.5 FEET NORTHWEST OF PIPE.*
- [06] BENTON COUNTY CORNER RESTORATION NO. 1113. *TRANSCRIBED FROM RECORD [05] AND MAY CONTAIN ERRORS AND/OR OMISSIONS.*
- [07] BENTON COUNTY SURVEY NOS. 3652 AND 5837 BY DAVID W. STEENSON, P.L.S., DATED MAY, 1962. *FOUND AND RESTORED.*
- [08] BENTON COUNTY SURVEY NO. 10485 BY JIM S. PETERSON, P.L.S., DATED JUNE 15, 2011. *FOUND 3" OSBF 1960 BRASS CAP. FOUND ROTTED FIR STUB (CSBT) BEARS N46°E, 56.1 FEET, NO MARKS VISIBLE; FIR 34" DIA BEARS S5-1/2°W, 3.0 FEET, HEALED FACE; FIR 30" DIA BEARS S40°E, 118.0 FEET, HEALED FACE; FIR 36" DIA BEARS N31°E, 52.4 FEET, HEALED FACE; FIR 18" DIA BEARS N66-1/2°W, 49.8 FEET, HEALED FACE.*

FIRM/AGENCY: BENTON COUNTY SURVEYOR'S OFFICE
ADDRESS: 360 S.W. AVERY AVE., CORVALLIS, OR 97333; PH. 541-766-6821
RESEARCH BY: DAVID L. MALONE, P.L.S.
DATA ENTRY BY: SAME

#28 ✓ Cor of Secs 7, 12, 13 + 18 T_p 13-5 & 4 W.
 Set 1/2" Galvanized pipe 30" long. tree and stump standing
 Maple 18" in diam bears N 66°-05 E. 62.8'
 Ash 10" " " " S 39-30 E. 25.7'
 Maple 11 " " " " N 86°-W. 18.2'
 Ash 12 " " " " S 61-30 W. 64.8'

" ✓ 1/4 Corner bet Secs 1 + 12 T_p 13-5.
 drove 3/4 x 7/8" galvanized iron pipe 1 tree standing
 An Oak 8" in diam bears N 11°-30' E 215.1'

" ✓ 1/4 corner bet Secs 6 + 7 T_p 13-5
 3/4" iron pipe, original oak on South standing.
 a Fir 15" in diam bears N 37-30 E 480 = 31.8'
 " " 15" " " " S. 83° E 278'

#30 ✓ N. E. cor of Andrew Foster D.L.C. T_p 13-5
 F.M.W. Set 24" section of sickle bar, 1st standing.
 an Oak 24" in diam bears N 7-30 E 71.9'
 " " 14" " " " N 15-55 W 118.9'

#31. ✓ 1/4 cor. bet. Secs 28 + 33 T_p 11-7
 F.M.W. a Fir 26" in diam, bears. S 19-40 W. 11.7
 " " 22" " " " N 21-20 W. 9.1
 Set Stone 2' x 8" x 6" Stump and tree down.

" Corner to Secs 28, 29, 32 + 33. T_p 11-7
 Set Thimble and box in of a 2 1/2" wagon. all trees down, no history
 a dead Fir. 44" in diam. bears N 46° E. 56.1'
 " " " 42" " " " S 68-25 E. 41.1'
 " " " 24" " " " S 42- W. 29.1'
 " " " 42" " " " N 76-20 W. 42.0'

" 1/4 Sec. Cor bet Secs 32 + 33 T_p 11-7
 Set stake, old trees almost gone.
 a Fir 15" in diam. bears S 49-30 E. 35.8'
 " " 12" in diam. " N 66-15 W. 31 + 3'

" Corner to Secs. 32, 33, 4 + 5 T_p 11-7 + T. 12-7
 Set 1/2" x 24" gas pipe, trees all gone but one in S. E.
 a Dead Fir 50" in diam. bears. N 62-30 E 80.6'

" 1/4 Sec. cor bet Secs 32 + 5. T_p 11-7 + T. 12-7
 Set Fir thimble stake 1' x 4' x 36" mld G.S. #31 " 1 dead tree standing.
 a Fir 5" in diam bears N 71-45 E. 21.25'
 " " 4" " " " S 27-55 W. 92.3' Vert 21°

" 1/4 Sec Cor bet Secs 29 + 32. T_p 11-7
 Cedar stake 4 x 4 x 36 mld G.S. Cedar stump standing.
 a Fir 30" in diam bears. S 92-55 W. 22.3'
 " " 14" " " " N 8-30 W. 43.4'



Corner to Sections 28, 29, 32, and 33, Twp. 11-7

1113

Reestablishment by F. M. Wilkes

Date 12-31-1908

1315

Set thimble and boxing of a 2½" wagon (Old trees down, no live tree)

Dead Fir 44" in diam bears N 46°-E	56.1 feet
Dead Fir 42" in diam bears S 68-25E	41.1 feet
Dead Fir 24" in diam bears S 42-W	24.1 feet
Dead Fir 42" in diam bears N 76-20W	42.0 feet

Re-established by L. W. Amort

June 14, 1960

SET 1½" x 36" Galv. Iron Pipe / 3" Bronze cap marked, "Oregon State Board of Forestry, T. 11 S., R. 7 W., Sec. 29, Sec. 28, Sec. 32, Sec. 33, 1960, R.E. 2311," 30" in ground from which:

1316

- 4" Fir bears S. 5° 30' W. 3.0 feet
Scribed T. 11 S., R. 7 W., Sec 32 BT
- 6" Fir bears S. 40° E. 118.0 feet
Scribed T. 11 S., R. 7 W., Sec 33, BT
- 4" Fir bears N. 31° E. 52.4 feet
Scribed T. 11 S., R. 7 W., Sec. 28, BT
- 5" Fir bears N. 66° 30' E. 49.8 feet
Scribed T. 11 S., R. 7 W., Sec. 29, BT, RE 2311

Oregon State Board of Forestry Metal Location Poster on 4" BT S. 5° 30' W.

SET 4" x 4" x 72" White painted Cedar Post 1.5 feet northwest of pipe

C.S. 3781

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 28, 29, 32 and 33, T11S, R7W, W.M., Benton County, Oregon.

ORIGINAL

(No evidence of original corner found)

RESTORED by F.M. Wilkes, December 31, 1908

Set 2 1/2" wagon thimble and Boxing (found in place) from which a:

- 44" dead fir bears N46°E 56.1 ft.; now badly decayed snag, no scribes remaining.
- 42" dead fir bears S68°25'E 41.1 ft.; now badly decayed stump.
- 24" dead fir bears S42°W 24.1 ft.; now rotted stump, no scribes.
- 42" dead fir bears N76°20'W 42.0 ft.; remains of stump.

RESTORED

X Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T11S R7W S29 S28 S32 S33 1960 RE2311", 30 inches in ground, and from which a:
in place of wagon axle

- 4" Fir bears S5 1/2°W 3.0 ft.; scribed T11S R7W S32 BT.
- 6" Fir bears S40°E 118.0 ft.; scribed T11S R7W S33 BT.
- 4" Fir bears N31°E 52.4 ft.; scribed T11S R7W S28 BT.
- 5" Fir bears N66 1/2°E 49.8 ft.; scribed T11S R7W S29 BT RE2311.

Oregon State Board of Forestry metal location poster on 4" BT S5 1/2°W.
Set 4 x 4 x 72" white painted Cedar post 1.5 feet Northwest of pipe.

Dated June 14, 1960

Restored by Billy E. Davis under my direction.
Billy E. Davis



Present and witnessed by D. Steenson
R. Penniman