

117400460

RESTORED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

North one sixteenth corner common to Sections 15 and 16, Township 11 South, Range 7 West, W.M., Benton County, Oregon.

ORIGINAL

3/4" iron pipe (County Survey 1945) (found in place) from which a:

12" Fir bears S55°20'W 17.5 lks.; now 13" snag S52°W 10.9' to face with scribe S199 visible on upper face & BT visible on lower face.

30" Fir bears N27°40'W 11.0 lks.; now 32" stump N32°W 6.0' to face with scribe S199 visible on upper face & B visible on lower face.

RESTORED

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY N 1/16 S16 S15 1973 RS563", 33 inches in ground, over 3/4" iron pipe, and from which a:

8" Grand Fir bears S04°E 7.0 ft. to face; scribed N1/16 S15 RS563 BT.

7" Grand Fir bears N67°W 31.9 ft. to face; scribed N1/16 S16 BT.

Fence corner running North and West bears SE 2.0 ft.

Set 4" x 4" x 72" white painted Cedar post 1.5 ft. NW of corner pipe. Oregon State Forestry Department metal location poster on 3" Grand Fir N12°E 2.2 ft.

Dated November 20, 1973

Restored by

William M. Bonsanti
William M. Bonsanti, Transitman

under my direction.

Present and witnessed by William E. Seeley

