

C.S. #278

Corner to Secs. 8, 9, 16 & 17 T. 12 S. R. 6 W.

Set Stone 12" x 12" x 15"

Oak 15" in dia. bears N. 1° 15' E. 1.26 chs. std. dead.

Maple 18" " " N. 4° 30' E. .592 "

Fir 32" " " S. 60° 30' E. .214 "

Oak 5" " " S. 34° 40' W. .494 "

" 6" " " S. 61° W. 1.38 " " "

Fir 50" " " N. 77° 30' W. 1.05 " " "

Witnesses W. E. Wood & Robert Gellatly June 9, 1919

1/4 sec. cor. bet. secs. 9 & 16. T. 12 S. R. 6 W.

Set Oak stake 5" x 4" x 30" both good trees oaks std. but dead.

Fir 14" in dia. bears N. 2° E. .144 chs.

" 11" " " S. 66° E. .137 "

Witnesses W. E. Wood & R. H. Gellatly June 10, 1919.

1/4 sec. cor. between secs. 16 & 21, T. 12 - 6.

Set 3/4" galv. pipe. Set half way between sec. cors.

Oak 24" in dia. bears N. 89° 50' E. 5.146 chs.

" 12" " " N. 42° 53' W. 5.179 "

Witnesses S. M. Wood & R. H. Gellatly June 11, 1919.

Cor. to secs. 15, 16, 21 & 22 T. 12 - 6

Set Stone 9" x 12" x 14". Measurements from oaks correct.

All bngs. from oaks nearly tally. Trees down

Fir 11" in dia. bears N. 9° E. .461 chs.

" 12" " " S. 22° E. .036 "

" 32" " " S 31° W. .104 "

Oak 4" " " N. 49 3/4° W. .283 "

Witnesses S. M. Wood & R. H. Gellatly. June 11, 1919.

C.S. #279

W. E. Gellatly

S. W. cor. of A. M. Rainwater Cl. # 39. T. 11 - 4

Pipe straddle set. I. Filed rock arround it, 3/4" rod NO. 11 W. 2.143 at 5.6' of pavement

Maple 48" in dia. N. 2° 20' E. 1.637 chs. Arough large hollow maple!

" 34" " " N 69° W. 4.556 "

Witnesses S. M. Wood June 18, 1919.

C.S. #68 cont.

W. E. G.

N. W. cor. of (Wm. Bennett) Stephen Gates Cl. 50. T. 13 - 6.

Set Stone 21" x 14" x 10" high @ corner. July 3, 1919.

Oak stump S 61° W. 3.88 chs. There was an other tree

in the field which they wanted to take out. so no new tree was used.

Mr. Gates as witness that the stone is where the orig. cor. was.

Buggy axle N 65 1/2° E. 6.252 chs. Other witness J. M. England

C.S. 245 cont.

Road #414.

W. E. G.

1/4 sec. cor. between secs. 25 & 26 T. 13 - 5.

Set 1 1/4" shift. Replaced old oak stake. No trees left as witnesses.

Oak 10" S. 50 1/2° E. .424 chs.

" 15" N. 6 1/2° E. 4.364 "

Witnesses C. E. Linton & Donald C. Patrick. Sept. 20, 1919.

C.S. 2
Road #C.S. 2
W. E. G.
Oct. 6, 1911Witnesses
W. E. Wood
R. H. Gellatly

†-Section corner between sections 16 and 21, Twp. 12-6 1395

Reestablishment by W. C. Galloway

June 11, 1919

Set $\frac{3}{4}$ " galvanized pipe, set halfway between section corners
Oak 24" in diam bears N 89° 50' E 5.146 chains
Oak 12" in diam bears N 42° 53' W 5.179 chains

Witnesses S. M. Wood and R. H. Gellatly

BENTON COUNTY SURVEYORS OFFICE - CORNER RESTORATION

03039

T. 12 S. R. 6 W. W. B. & M., BENTON COUNTY, OREGON


SECTION 16

The information shown hereon was taken from
the referenced county survey. Date: 7/21/90

REPORTED BY NEAL PETERSON

TITLE L.S. 1496

DATE 7-8-1982



● OFFICIAL CORNER FOUND

○ CORNER SET

1/4 CORNER COMMON TO SEC. 16 & 21
3/4" I.B. PIPE AS PER GALLOWAY
DESCRIBE

ADDITIONAL INFORMATION

C.S. 278

SEE C.S. 7450

OVER

LEGIBLE MARKS ON BEARING OBJECTS

KIND			
SIZE			
BEARING			
DISTANCE			
BT TAG POSTED			

126340400

BENTON COUNTY SURVEYORS OFFICE - CORNER RESTORATION

3314


T 12 S, R 6 W, W. B. & M., BENTON COUNTY, OREGON

REPORTED BY JOHN RINALDI, JR.

SECTION 16

TITLE BENTON COUNTY SURVEY CREW CHIEF

DATE JANUARY 31, 1985



● OFFICIAL CORNER FOUND

○ CORNER SET

1/4 CORNER COMMON TO SEC. 16 & 21

DESCRIBE

ADDITIONAL INFORMATION

FOUND 3/4" (INNER DIA.) IRON PIPE, 12" BELDIE GROUND SURFACE, PER CORNER RESTORATION CARD N° 1395 AND C.S. 7182. FOUND ALSO A 24" OAK STUMP 4' TALL, AT N. 42° 53' W. 341.5' (WAS 12" OAK AT N. 42° 53' W. 341.81' PER SAID CORNER RESTORATION CARD). PIPE WAS IN GOOD CONDITION AND LEFT IN PLACE.

OVER

LEGIBLE MARKS ON BEARING OBJECTS

	FOUND	FOUND	SET	SET
			B _T	B _T
KIND	WHITE OAK	IRON ROD	DOUG. FIR	DOUG. FIR
SIZE	24" DIA. STUMP, 4' TALL	5/8"	16" DIA.	12" DIA.
BEARING	N. 42° 53' W.	S. 30° 25' 48" E	N. 73° 9' E.	N. 62° 26' W.
DISTANCE	341.5'	188.30'	857.5'	937.7'
BT TAG POSTED	YES	NO	YES	YES

IRON ROD FOUND PER C.S. 7182.

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON JULY 15, 1983 JOHN RINALDI, JR. 2056