

127160620

BENTON COUNTY SURVEYORS OFFICE - CORNER RESTORATION

1616

T. 12 S. R. 7 W. W. B. & M., BENTON COUNTY, OREGON

REPORTED BY LES ROBERTS

SECTION 6

TITLE P.L.S. 1039

DATE DEC. 29, 1980



- OFFICIAL CORNER FOUND
- CORNER SET

S.E. 1/6 CORNER COMMON TO SEC. 6
 IS 3/4" IRON PIPE AND 4" X 4" WHITE POST.
DESCRIBE

ADDITIONAL INFORMATION
 FOUND 3/4" IRON PIPE SET BY
 GALLOWAY IN SURVEY NO. 74
 DATED 1910. FOUND 2 ORIGINAL
 B.T.'S. SET 2 NEW B.T.'S
 B.T.'S ARE SCRIBED AND
 DISTANCES ARE CENTER
 MEASURE.

OVER

LEGIBLE MARKS ON BEARING OBJECTS

	(SCAR VIS.)	(SCAR VIS.)		
	1910 B.T.	1910 B.T.	NEW B.T.	NEW B.T.
KIND	FIR	FIR STUMP	FIR	FIR
SIZE	36"	54"	14"	36"
BEARING	N72W	S18W	N35E	N72W
DISTANCE	9'	48'	22'	9'
BT TAG POSTED	YES	NO	YES	YES