## 

## BENTON COUNTY CORNER HISTORY FORM, PAGE 1 OF 1,

137200500H

DATE 08/06/2020

TOWNSHIP 13 SOUTH, RANGE 7 WEST, WILLAMETTE MERIDIAN; SECTION 7 CORNER SOUTHEAST DONATION LAND CLAIM N/A CORNER N/A

## **COMMON CORNER(S):**

SOUTHWEST CORNER SECTION 8
NORTHWEST CORNER SECTION 17
NORTHEAST CORNER SECTION 18

## RECORDS (INFORMATION IN BOLD ITALICS IS COUNTY STAFFS' INTERPRETATION OF THE RECORD)

BASED ON EXTENSIVE RESEARCH AND RECOVERY OF EVIDENCE, THIS OFFICE HAS DETERMINED THAT MOST GENERAL LAND OFFICE SURVEYORS IN BENTON COUNTY BEFORE 1890 MEASURED TO THE FACE OF BEARING TREES.

- [01] GENERAL LAND OFFICE (GLO) NOTES BY ROBERT O. COLLIER, D.S., DATED FEBRUARY 9, 1892. SET A STONE 12" X 10" X 8", 8" IN GROUND, MARKED WITH 4 NOTCHES ON SOUTH EDGE AND 5 NOTCHES ON EAST EDGE, FROM WHICH A FIR 40" DIA BEARS N33°E, 48 LINKS (31.68 FEET), MARKED "T13SR7WS8BT"; FIR 20" DIA BEARS S46°E, 74 LINKS (48.84 FEET), MARKED "T13SR7WS17BT"; FIR 18" DIA BEARS N53°W, 57 LINKS (37.62 FEET), MARKED "T13SR7WS7BT".
- [02] BENTON COUNTY SURVEY NO. 8105 BY NORMAN D. SPRINGER, P.L.S., DATED FEBRUARY 10, 1988. FOUND STONE 12" x 8" x 10", 4 NOTCHES ON SOUTH EDGE, 5 NOTCHES ON EAST EDGE. FIR SNAG 18" DIA (GLO BT) BEARS N53°W, 37.6 FEET, NO MARKS; FIR SNAG 40" DIA (GLO BT) BEARS N33°E, 31.6 FEET, NO MARKS; FIR SNAG 24" DIA (GLO BT) BEARS S46°E, 48.8 FEET, NO MARKS; FIR SNAG STUB 18" DIA (GLO BT) BEARS S24°W, 70.6 FEET, NO MARKS. SET 5/8" x 30" IRON ROD WITH 2" ALUMINUM CAP MARKED "T13S R7W S7 S8 S18 S17 LS1102 1988". DEPOSIT ORIGINAL STONE ALONGSIDE. FIR 14" DIA BEARS N31°E, 22.8 FEET, SCRIBED "T13SR7WS8BT"; FIR 14" DIA BEARS S32°E, 4.6 FEET, SCRIBED "T13SR7WS17BT"; FIR 18" DIA BEARS S87°W, 6.9 FEET, SCRIBED "T13SR7WS18BT"; FIR 16" DIA BEARS N67°W, 15.5 FEET, SCRIBED "T13SR7WS7BT".
- [03] BENTON COUNTY CORNER RESTORATION NO. 3500. TRANSCRIBED FROM RECORD [02] AND MAY CONTAIN ERRORS AND/OR OMISSIONS.
- [04] BUREAU OF LAND MANAGEMENT (BLM) NOTES BY ROBERT L. AARSETH AND JANET R. MYERS, CADASTRAL SURVEYORS, DATED APRIL 4, 2005. THE SECTION CORNER MONUMENTED WITH AN IRON ROD, 5/8" DIA, FIRMLY SET, PROJECTING 1" ABOVE GROUND, WITH ALUMINUM CAP MARKED "T13SR7W S7 S8 S18 S17 LS1102 1988", FROM WHICH A FIR STUMP (GLO BT), SIZE INDETERMINATE, BEARS N33°E, 31.7 FEET, WITH NO MARKS VISIBLE; FIR SNAG (GLO BT), SIZE INDETERMINATE, BEARS S46°E, 48.8 FEET, WITH NO MARKS VISIBLE; FIR STUMP (GLO BT), SIZE INDETERMINATE, BEARS S24°W, 70.6 FEET, WITH NO MARKS VISIBLE; FIR 15" DIA BEARS N31°E, 22.8 FEET, WITH HEALED BLAZE; FIR 14" DIA BEARS S32°E, 4.6 FEET, WITH HEALED BLAZE; FIR 20" DIA BEARS S87°W, 6.9 FEET, WITH HEALED BLAZE; FIR 16" DIA BEARS N67°W, 15.5 FEET, WITH HEALED BLAZE. AT THE CORNER POINT SET A STAINLESS STEEL POST, 28" LONG, 2-1/2" DIA, 19" IN THE GROUND, DIRECTLY OVER IRON ROD AND ALUMINUM CAP, AND IN A MOUND OF STONE, 2 FOOT BASE, 8" HIGH, WITH BRASS CAP MARKED "T13S R7W S7 S8 S18 S17 2000".

FIRM/AGENCY: BENTON COUNTY SURVEYOR'S OFFICE

ADDRESS: 360 s.w. avery ave., corvallis, or 97333; ph. 541-766-6821

RESEARCH BY: DAVID L. MALONE, P.L.S.

**DATA ENTRY BY: SAME** 

OREGON CORNER RESTORATION FORM		13720050
Section <u>/8</u> Township	1011000	
County BENTON	Date2//0/1988	
S7 5 S/8 5 A	<u>8</u> /7 etc	Condition Report Only Not Found Renewed Unrecorded Surveyed In Referenced Out
Monument(s) & Accessories	Found: (Condition and Sou	
• •	·	S. EDGE, SNOTCHES ON E. ED
		O MARKS;
	•	MARKS;
	· ·	JO MARKS;
18" FIR STUE	3 524 W, 70.6 FT, N	O MARKS.
Monument Detail		Sketch
CS 8105		
Monument Set (Procedures a	nd Description)	
5/8" IRON ROD W	1174 2" ALUMINUM	CAP
DEPOSITED ORIGINA	L STONE ALONGS!	DE
New Assessmen		
New Accessories	22 8 ST SCRIBED "TI	3S R7W 58 BT";
•	ř.	35 R7W S/7 BT";
	•	735 R74/518 BT ";
	·	135R7W 57BT".
Location & Comments		Surveyor's Seal
	Compass Declination	
	Firm/Agency SPRING	
	SURVEYING	
	•	
	Address Address Party Chief Notes	EGON

Witness