

137440200

DATE 08/03/2020TOWNSHIP 13 SOUTH, RANGE 7 WEST, WILLAMETTE MERIDIAN; SECTION 27 CORNER SOUTH 1/4
DONATION LAND CLAIM N/A CORNER N/A**COMMON CORNER(S):**

NORTH 1/4 CORNER SECTION 34

RECORDS (INFORMATION IN *BOLD ITALICS* IS COUNTY STAFFS' INTERPRETATION OF THE RECORD)

BASED ON EXTENSIVE RESEARCH AND RECOVERY OF EVIDENCE, THIS OFFICE HAS DETERMINED THAT MOST GENERAL LAND OFFICE SURVEYORS IN BENTON COUNTY BEFORE 1890 MEASURED TO THE FACE OF BEARING TREES.

- [01] GENERAL LAND OFFICE (GLO) NOTES BY ROBERT O. COLLIER, D.S., DATED FEBRUARY 9, 1892. *SET A POST 3 FEET LONG, 3" SQUARE, 24" IN THE GROUND, MARKED "1/4S" ON NORTH FACE FROM WHICH A DOGWOOD 5" DIA BEARS N52°E, 43 LINKS (28.38 FEET), MARKED "1/4S BT"; FIR 24" DIA BEARS S38°E, 47 LINKS (31.02 FEET), MARKED "1/4S BT".*
- [02] BUREAU OF LAND MANAGEMENT (BLM) NOTES BY ROBERT L. AARSETH, CADASTRAL SURVEYOR, DATED AUGUST 31, 2003. *THE 1/4 SECTION CORNER DETERMINED AT RECORD BEARING AND DISTANCE FROM THE REMAINING ORIGINAL BEARING TREE, A FIR 60" DIA (GLO BT) BEARS S38°E, 31.0 FEET, WITH SCRIBE MARKS "1/4S" VISIBLE ON A PARTIALLY OPENED BLAZE. AT THE CORNER POINT SET A STAINLESS STEEL POST, 28" LONG, 2-1/2" DIA, 24" IN THE GROUND, WITH BRASS CAP MARKED "T13S R7W S27 1/4 S34 2003" FROM WHICH A FIR 10" DIA BEARS N65°E, 20.6 FEET TO A 2-1/2" X 1/4" MAGNETIC NAIL (MAG NAIL) DRIVEN AT THE BASE ON RIGHT SIDE CENTER, MARKED "1/4 S27 BT"; FIR 13" DIA BEARS SOUTH, 42.3 FEET TO A MAG NAIL DRIVEN AT THE BASE ON RIGHT SIDE CENTER, MARKED "1/4 S34 BT". DEPOSIT A MAGNET IN A WHITE PLASTIC CASE AT THE BASE OF THE STAINLESS STEEL POST.*

FIRM/AGENCY: BENTON COUNTY SURVEYOR'S OFFICE
ADDRESS: 360 S.W. AVERY AVE., CORVALLIS, OR 97333; PH. 541-766-6821
RESEARCH BY: DAVID L. MALONE, P.L.S.
DATA ENTRY BY: SAME