


R. AARSETH / J. MYERS

2000

36 145

**Dependent Resurvey of a Portion of Donation Land Claim No. 37,  
T. 13 S., R. 7 W., Willamette Meridian, Oregon**

FEET	
	An iron rod, 5/8 in. diam., bears N. 82½° E., 21.91 ft. dist., firmly set, with top 1 in. below the surface of the ground, with red plastic cap mkd. BENTON COUNTY SURVEYOR'S OFFICE.
	A fir, 21 ins. diam., bears S. 6¾° W., 37.2 ft. dist., with scribe marks DLC 37 BT visible on open blaze.
	An iron rod, 5/8 in. diam., bears S. 80¾° W., 20.56 ft. dist., firmly set, with top 1 in. below the surface of the ground, with red plastic cap mkd. BENTON COUNTY SURVEYOR'S OFFICE.
	An iron rod, 5/8 in. diam., bears N. 22° W., 22.95 ft. dist., firmly set, with top 1 in. below the surface of the ground, with red plastic cap mkd. BENTON COUNTY SURVEYOR'S OFFICE.
	An orange carsonite post is located North, 1 ft. dist.
	From the NE. cor. of Donation Land Claim No. 37, a local point set as the NE. cor. of Donation Land Claim No. 37, by Bruce Starker, Registered Land Surveyor No. 310, in 1955, and recorded in Benton County Corner Restoration No. 2105, bears S. 17° 35' E., 4.03 ft. dist., monumented with an iron pipe, ½ in. diam., firmly set, projecting 6 ins. above ground.
	This point is not properly positioned and is not utilized in this survey.
<hr/> <p><b>Dependent Resurvey of a Portion of Donation Land Claim No. 38, T. 13 S., R. 7 W., Willamette Meridian, Oregon</b></p> <hr/>	
<p>(Restoring the survey by Dennis Hathorn in 1856)</p> <hr/>	
	From the ¼ sec. cor. of secs. 29 and 32.
	N. 0° 19' 30" W., on the E. bdy. of Donation Land Claim No. 38.
	Descend over gentle N. slope, through moderate timber and undergrowth.
1319.68	A local corner, established by W. C. Galloway, County Surveyor, in 1911, and recorded in Benton County Survey No. G13700003, and is accepted as a point on line, monumented with an iron rod, ¼ in. diam., firmly set, projecting 10 ins. above ground.
<p>1378 38070</p> 	This now becomes an angle point.
	Place an aluminum cap upon the iron rod mkd.

R. AARSETH / J. MEYERS

2000

37 146

**Dependent Resurvey of a Portion of Donation Land Claim No. 38,  
T. 13 S., R. 7 W., Willamette Meridian, Oregon**

FEET	
	N. 0° 20' 00" W., beginning new measurement.
	Descend over NW. slope.
600	Left bank of Alsea River, edge bears N. 80° W. and S. 80° E., course N. 80° W.; thence across river.
650	Right bank of Alsea River, edge bears; N. 80° W. and S. 80° E.; asc. over SE. slope.
973.26	The NE. corner of Donation Land Claim No. 38.
<hr/> <p><b>Subdivision of Section 21, T. 13 S., R. 7 W., Willamette Meridian, Oregon</b></p> <hr/>	
	From the ¼ sec. cor. of secs. 21 and 28.
	N. 0° 10' 00" E., on the N. and S. centerline of section 21.
	Ascend over gentle SE. slope, through moderate timber and undergrowth.
35	Lake Lyons Road, graveled surface, 15 ft. wide, bears N. 15° W. and S. 15° E.
265	Crooked Creek, 30 ft. wide, course S. 70° W.; asc. over SE. slope.
615	Alsea State Highway No. 27, Route No. 34, asphalt surface, 50 ft. wide, bears N. 35° E. and S. 35° W.
989.69	A local corner established by W. C. Galloway, County Surveyor, in 1926, and recorded in Benton County Survey No. G13700002, monumented with an iron rod, 7/8 in. diam., firmly set, projecting 1 in. above ground, alongside of which is an iron pipe, 1 in. diam., firmly set, projecting 2 ins. above ground.
1329.95	The center S 1/16 sec. cor. of sec. 21, established by W. C. Galloway, County Surveyor, in 1926, and recorded in Benton County Survey No. G13700002, subsequently perpetuated by Theodore James Langton, Registered Land Surveyor No. 1823, in 1998, and recorded in Benton County Survey No. 9365, and is accepted as the corner, monumented with an iron rod, 7/8 in. diam., firmly set, projecting 2 ins. above ground, from which the bearing trees mkd. by Langton