

138100140

DATE 01/05/2021TOWNSHIP 13 SOUTH, RANGE 8 WEST, WILLAMETTE MERIDIAN; SECTION 31 CORNER WEST 1/4
DONATION LAND CLAIM N/A CORNER N/A**COMMON CORNER(S):**

EAST 1/4 CORNER SECTION 36, TOWNSHIP 13 SOUTH, RANGE 9 WEST

RECORDS (INFORMATION IN *BOLD ITALICS* IS COUNTY STAFFS' INTERPRETATION OF THE RECORD)

BASED ON EXTENSIVE RESEARCH AND RECOVERY OF EVIDENCE, THIS OFFICE HAS DETERMINED THAT MOST GENERAL LAND OFFICE SURVEYORS IN BENTON COUNTY BEFORE 1890 MEASURED TO THE FACE OF BEARING TREES.

- [01] GENERAL LAND OFFICE (GLO) NOTES BY EDWARD F. SHARP, D.S., DATED SEPTEMBER 25, 1897. *SET AN ALDER POST, 3 FEET LONG, 3" SQUARE, 24" IN THE GROUND, MARKED "1/4S" ON WEST FACE, FROM WHICH AN ALDER 8" DIA BEARS S20°E, 52 LINKS (34.32 FEET), MARKED "1/4S BT"; FIR 8" DIA BEARS S31°W, 18 LINKS (11.88 FEET), MARKED "1/4S BT".*
- [02] NOTES FOR RESTORATION OF CORNER FROM LEO J. MARTIN, P.L.S., DATED NOVEMBER 10, 1964, ALSO FILED AS LINCOLN COUNTY SURVEY NO. 2440. *FOUND D. FIR 44" DIA (GLO BT) BEARS S31°W, 18 LINKS (11.88 FEET), CHOPPED OPEN TO REVEAL SCRIBE MARKS, SCRIBED "363" ON CLEAN PORTION OF CHOPPED OPEN FACE; ALDER 12" DIA (GLO BT) BEARS S20°E, 36.0 FEET ON SLOPE, ROTTED OUT FACE WHERE IT WAS CHOPPED OPEN SEVERAL YEARS AGO. D. FIR 36" DIA BEARS N83°E, 59.8 FEET, SCRIBED "363 1/4 S 31 BT". SET 3/4" X 36" GALVANIZED IRON PIPE.*
- [03] BENTON COUNTY CORNER RESTORATION NO. 2135. *TRANSCRIBED FROM RECORD [02] AND MAY CONTAIN ERRORS AND/OR OMISSIONS.*
- [04] BENTON COUNTY SURVEY NO. 6432 BY FRED I. LEMKE, P.L.S., DATED JUNE 6, 1977. *FOUND 3/4" PIPE FROM WHICH A FIR 48" DIA (GLO BT) BEARS S31°W, 0.18 CHAINS (11.9 FEET) TO FACE, RESCRIBED "363" BY MARTIN; FIR 40" DIA BEARS N84°09'E, 58.8 FEET TO NAIL ABOVE FACE.*
- [05] LINCOLN COUNTY SURVEY NO. 13904 BY DAVID A. LOOMIS, P.L.S., DATED AUGUST, 1992. *FOUND 1" IRON PIPE. FIR 48" DIA (GLO BT) BEARS S31°W, 12 FEET; FIR 42" DIA BEARS N33°E, 36 FEET.*
- [06] LINCOLN COUNTY SURVEY NO. 14658 BY DAVID A. LOOMIS, P.L.S., DATED AUGUST, 1992. *FOUND 1" IRON PIPE. FIR 48" DIA (GLO BT) BEARS S31°W, 12 FEET; FIR 42" DIA BEARS N33°E, 36 FEET.*

FIRM/AGENCY: BENTON COUNTY SURVEYOR'S OFFICE
ADDRESS: 360 S.W. AVERY AVE., CORVALLIS, OR 97333; PH. 541-766-6821
RESEARCH BY: DAVID L. MALONE, P.L.S.
DATA ENTRY BY: SAME

NEW

SEE (OR. REST. No. 2135
(CJL 7/23/90).

Notes for Restoration of Corners
in T. 13 S., R. 8 and 9 W., W.M.

1/4 section corner between sections 36 and 31.

Found: *D. Fir 44", S 31° W, 18 Lks. We chopped open to reveal scribe marks.

Alder 12", S 20° E, 36.0 ft. on slope.

This alder has a rotted out face where it was chopped open several years ago.

Scribed: D. Fir 36", N 83° E, 59.8 ft. (363 1/4 S 31 BT)

*Scribed (363) on clean portion of chopped open face of original S.W. B.T.

Set: 3/4" x 36" galvanized iron pipe.



13-8-31

13-9-36

Quarter corner between Sections 36 & 31, Twp. 13S, R 8 & 9 W

2135

Reestablishment by Leo Martin

1964

3/4"x36" Pipe

D. Fir 44" in diam bears S 31° W 18 lks

Alder 12" in diam bears S 20° E 36.0 ft on slope

D. Fir 36" in diam bears N 83° E 59.8 ft

FOR ADDITIONAL INFORMATION SEE THE T13S RBW FILE IN THE CORNER
RESTORATION CORRESPONDENCE FILE DRAWER.