

**145540700**

DATE 11/21/2003TOWNSHIP 14 SOUTH, RANGE 05 WEST, WILLAMETTE MERIDIAN; SECTION 02 CORNER NORTH 1/4  
DONATION LAND CLAIM N/A CORNER N/A**COMMON CORNER(S):**

POINT ON SOUTH LINE OF SECTION 35, TOWNSHIP 13 SOUTH, RANGE 5 WEST

**RECORDS (INFORMATION IN *BOLD ITALICS* IS COUNTY STAFFS' INTERPRETATION OF THE RECORD)**

BASED ON EXTENSIVE RESEARCH AND RECOVERY OF EVIDENCE, THIS OFFICE HAS DETERMINED THAT MOST GENERAL LAND OFFICE SURVEYORS IN BENTON COUNTY MEASURED TO THE FACE OF BEARING TREES.

- [01] GENERAL LAND OFFICE (GLO) NOTES BY JAMES E. FREEMAN, D.S., DATED DECEMBER 1, 1852. *SET POST FROM WHICH A W. OAK 15" DIA BEARS S10°E, 222 LINKS (146.52 FEET); W. OAK 10" DIA BEARS S50°W, 225 LINKS (148.50 FEET).*
- [02] BENTON COUNTY ROAD NO. 35022 (OLD NO. 359) FIELD NOTES (FIELD BOOK 18, PAGE 78) BY W. C. GALLOWAY, C.S., NO DATE GIVEN. *SET 3/4" PIPE. SOUTHEAST OAK GONE. OAK 10" DIA (GLO BT) BEARS S50°W, 2.25 CHAINS (148.50 FEET), STANDING. OAK 10" DIA BEARS S33°15'E, 0.428 CHAINS (28.25 FEET).*
- [03] BENTON COUNTY CORNER RESTORATION BOOK NO. 1, PAGE 94 BY W. C. GALLOWAY, C.S., DATED APRIL 24, 1915. *SET 3/4" PIPE. SOUTHEAST OAK GONE, WAS IN FIELD. OAK 10" DIA (GLO BT) BEARS S50°W, 2.25 CHAINS (148.50 FEET), STANDING. OAK 10" DIA (CSBT) BEARS S33°15'E, 0.428 CHAINS (28.25 FEET).*
- [04] BENTON COUNTY CORNER RESTORATION NO. 2200. *TRANSCRIBED FROM RECORD [03] AND MAY CONTAIN ERRORS AND/OR OMISSIONS.*
- [05] BENTON COUNTY MAP NO. 13-5-00017 BY W. C. GALLOWAY, C.S., DATED APRIL/OCTOBER, 1915. *3/4" PIPE. OAK 10" DIA (GLO BT) BEARS S50°W, 2.25 CHAINS (148.50 FEET), STANDING; OAK 10" DIA (CSBT) BEARS S33°15'E, 0.428 CHAINS (28.25 FEET).*
- [06] BENTON COUNTY SURVEY NO. 2934 BY HAROLD W. POLING, REG. ENGR., DATED FEBRUARY, 1957. *CORNER TIED, NO DESCRIPTION GIVEN.*
- [07] BENTON COUNTY LOOSE LEAF FIELD NOTES FOR ROUTE 22, SECTION B, 1957 BRIDGE CHANGE, COUNTY ROAD NO. 35220, BY RICHARD W. FAIL, P.L.S., DATED 1957. *FOUND 3/4" IRON PIPE.*

**FIRM/AGENCY:** BENTON COUNTY SURVEYOR'S OFFICE  
**ADDRESS:** 360 S.W. AVERY AVE., CORVALLIS, OR 97333; PH. 541-766-6821  
**RESEARCH BY:** BERNARD S. ALTENBACH, ENGINEER/SURVEY TECH.  
**DATA ENTRY BY:** BSA

## CORNER RESTORATION BOOK NO. 1

St. Road # 359 S.W. corner of Robt. D. Grimsley Ct. # 49 T. 13 S. R. 5 W.  
 Stone 6" x 10" x 9" already set.  
 In fence row both N, S, & E.

CS. #22

D. Wilkes  
Dep. CS

Witness Hugh Taylor April 27, 1915.

Cor. to Secs. 34 & 35 on 3<sup>rd</sup> std. parallel T. 13 S. R. 5 W.

Set 3/4" pipe

Ash 8" bears S. 65° 35' W. 1.848 chs.

Forked, 14" " N 62° W. 1.414 "

Witness Hugh Taylor April 28, 1915.

Cor. to secs. 2 & 3 on 3<sup>rd</sup> std. parallel T. 14 S. R. 5 W.

Set 3/4" pipe

Ash 15" bears N. 24° 22' W. 8.806 chs.

Witness Hugh Taylor April 28, 1915.

1/4 sec. cor. on S. of sec. 35 3<sup>rd</sup> std. parallel T. 13 S. R. 5 W.

Set 3/4" pipe

Ash 32" in dia. bears N. 6° E. .717 chs.

" 11" " " N. 44° 30' W. .477 "

Witness Hugh Taylor April 28, 1915.

1/4 sec. cor. on N. of sec. 2-3<sup>rd</sup> std. parallel T. 14 S. R. 5 W.

Set 3/4" pipe S.E. oak gone was in field.

Oak 10" bears S. 33° 15' E. .428 chs.

" 10" " S. 50° W. 2.25 " std.

Witness Hugh Taylor April 24, 1915.

Cor. to secs. 35 & 36 on 3<sup>rd</sup> std. parallel T. 13 S. R. 5 W.

Set 3/4" pipe N.W. oak stump.

Oak 24" bears N. 15° E. 3.27 chs. std.

" 8" " N. 15° W. 3.871 "

Witness Hugh Taylor April 24, 1915.

Cor. to secs. 1 & 2 on 3<sup>rd</sup> std. parallel T. 14 S. R. 5 W.

Set 3/4" pipe

Ash 8" bears S. 77° W. 3.20 chs. std.

Witness Hugh Taylor April 28, 1915.

1/4 sec. cor. on N. of sec. 1 T. 14 S. R. 5 W.

Set a 3/4" pipe Maple stump close check.

Ash 13" bears S. 51° 15' W. .582 chs.

" 11" " N 44° 40' W. .677 "

Witness Hugh Taylor April 29, 1915.

CS. #242

Cor. to secs. 27, 28, 33 &amp; 34 T. 14 S. R. 5 W.

Set 1 1/4" pipe replaced a stake

Oak 10" bears N. 2° E. 1.00 chs. std.

" 24" " S. 72° 30' E. 3.286 "

" 14" " S 86° W. 1.37 " "

" 12" " N. 42° 15' W. .75 " "

Witnesses J. M. Gillis &amp; Frank Curry May 17, 1915.

1/4 sec. cor. between secs. 27 &amp; 34 T. 14 S. R. 5 W.

Set 3/4" galv. pipe 10" under surface

Ash 24" bears N. 67° E. 4.77 chs. std. Eng. taken from line Temhd. Ash  
Ash is hollow and 40" in dia.

Witnesses J. M. Faris &amp; Miller June 8, 1915.

$\frac{1}{4}$ -Section corner on N of section 2-3rd std. parallel, Twp. 14 S., R. 5 W. <sup>200</sup>

Reestablishment by W. C. Galloway

April 24, 1915 2633

Set  $\frac{3}{4}$ " pipe

S. E. Oak gone, was in field.  
Oak 10" in diam bears S 33° 15' E  
Oak 10" in diam bears S 50° W

.428 chains  
2.25 chains (standing)

Witness Hugh Taylor