

145841020

DATE 11/20/2007TOWNSHIP 14 SOUTH, RANGE 05 WEST, WILLAMETTE MERIDIAN; SECTION 09 CORNER N/A
DONATION LAND CLAIM DAVID C. BELCHER NO. 41 CORNER EAST-SOUTHEASTCOMMON CORNER(S):

NONE

RECORDS (INFORMATION IN ***BOLD ITALICS*** IS COUNTY STAFFS' INTERPRETATION OF THE RECORD)

BASED ON EXTENSIVE RESEARCH AND RECOVERY OF EVIDENCE, THIS OFFICE HAS DETERMINED THAT MOST GENERAL LAND OFFICE SURVEYORS IN BENTON COUNTY MEASURED TO THE FACE OF BEARING TREES.

- [01] GENERAL LAND OFFICE (GLO) NOTES OF THE DAVID C. BELCHER DONATION LAND CLAIM (DLC) NO. 41 BY DENNIS HATHORN, D.S., DATED DECEMBER 24, 1853. ***SET POST FROM WHICH A W. OAK 15" DIA BEARS S79-1/2°W, 728 LINKS (480.48 FEET); A W. OAK 20" DIA BEARS N70-3/4°W, 549 LINKS (362.34 FEET).***
- [02] BENTON COUNTY SURVEY NO. 409 (OLD NO. 180) FIELD NOTES (BOOK 15, PAGE 66) BY W. C. GALLOWAY, C.S., DATED NOVEMBER 10, 1913. ***SET 1-1/4" PIPE, 10" UNDER SURFACE, ORIGINAL CORNER. OAK 20" DIA (GLO BT) BEARS N70°45'W, 5.49 CHAINS (362.34 FEET), STANDING. OAK 12" DIA BEARS N34°35'W, 4.294 CHAINS (283.40 FEET).***
- [03] BENTON COUNTY CORNER RESTORATION BOOK NO. 1, PAGE 181 BY W. C. GALLOWAY, C.S., DATED NOVEMBER 10, 1913. ***SET 1-1/4" PIPE, 10" UNDER SURFACE, ORIGINAL CORNER. OAK 20" DIA (GLO BT) BEARS N70°45'W, 5.49 CHAINS (362.34 FEET), STANDING. MARKED OAK 12" DIA (CSBT) BEARS N34°35'W, 4.294 CHAINS (283.40 FEET).***
- [04] BENTON COUNTY CORNER RESTORATION NO. 2285. ***TRANSCRIBED FROM RECORD [03] AND MAY CONTAIN ERRORS AND/OR OMISSIONS.***
- [05] BENTON COUNTY MAP NO. 14-5-00008 BY W. C. GALLOWAY, C.S., DATED MAY 29, 1917. ***1-1/4" PIPE, 10" UNDER SURFACE. OAK 20" DIA (GLO BT) BEARS N70°45'W, 5.49 CHAINS (362.34 FEET), STANDING. OAK 12" DIA (CSBT) BEARS N34°35'W, 4.294 CHAINS (283.40 FEET).***
- [06] BENTON COUNTY MAP NO. 14-5-00003 BY W. C. GALLOWAY, C.S., DATED NOVEMBER 5, 1920. ***1-1/4" PIPE, 10" UNDER SURFACE.***
- [07] BENTON COUNTY SURVEY NO. 1115 FIELD NOTES (BOOK 76, PAGE 5) BY W. W. LARSEN, D.C.S., NO DATE GIVEN. ***1-1/4" PIPE, 10" UNDER SURFACE. OAK 20" DIA (GLO BT) BEARS N70°45'W, 5.49 CHAINS (362.34 FEET). OAK 12" DIA (CSBT) BEARS N34°35'W, 4.294 CHAINS (283.40 FEET).***

FIRM/AGENCY: BENTON COUNTY SURVEYOR'S OFFICE
ADDRESS: 360 S.W. AVERY AVE., CORVALLIS, OR 97333; PH. 541-766-6821
RESEARCH BY: BERNARD S. ALTENBACH, ENGINEER/SURVEY TECH.
DATA ENTRY BY: SAME

CORNER RESTORATION BOOK NO. 1

C.S. 180
by W.C. Galloway C.S.
Nov. 10, 1913
Witnesses
James M. Herron

Witness Corner 1 chain East of N.W. cor. of Wm. Barclay Cl. 14-5
Set 1 1/2" pipe stake found
Oak 24" in dia. bears S 67° W .76 chs. std.
" 12" " " " S 15° E 2.04 " "
Set 1 1/4" pipe .758 chs. West of Claim corner.

N.E. corner of David Belcher D.L.C. #41 T. 14 S. R 5 W
Set 1 1/4" galvanized iron pipe. Orig. cor.
Ash 10" in dia. bears S. 9 1/2° E. 2.59 chs. standing
Oak 5" " " " N 0° 19' W. 1.23 " "

Most East S.E. cor. of David Belcher Cl. 41 T 14-5
Set 1 1/4" pipe 10" under the surface. orig. cor.
Oak 20" in dia. bears N 70° 45' W. 5.49 chs. std.
Mkd. " 12" " " " N 34° 35' W. 4.294 "

Interior Cor. to David Belcher Cl. 41 T 14-5
Set 1 1/4" pipe
Ash 10" in dia. bears N 88° E 6.84 chs. std.
" 12" " " " S. 53 1/2° E 5.75 " "

S.E. or most S. S.E. cor. of David Belcher Cl. 41 T. 14-5
Set 1 1/4" pipe from stump hole of ash and
Mkd. Double Thorn 10" in diameter bears S. 65° 15' W. .768 chs.
Original Oak 20" " " " N. 12° 15' W. 9.75 " standing

S.W. corner of David Belcher D.L.C. 41 T 14-5
Set 1 1/4" shaft
Mkd. Thorn 6" in dia. bears N 88° 10' E .272 chs.
" Ash 12" " " " S 39° 15' W. .992 "

S.E. cor. of Wm Barclay D.L.C. T. 14-5
Set 3/4" pipe original corner
Oak 4" in dia. bears N. 4° E .41 chs. std.
Mkd. " 7" " " " S. 85° 40' E. 2.97 chs.
Pine " " " " S 57° 30' W 2.0 " "

Road Survey
W.C. Galloway C.S.
March 26, 1926
Witnesses
Carl Peterson and
Byron K. Taylor
Aisca Highway
Survey
W.C. Galloway C.S.

1/2" ^{Pop over} Corner to Secs. 15, 16, 21 & 22 T. 13-7
Set boulder in place of stone that was badly decayed and crumbled.
Fir 36" in dia. bears S. 18° E .94 chs. std.
" 14" " " " S 32 1/2° W 2.50 " " not checked
" 30" " " " N. 49° W. 2.33 " " "

1/4 sec. cor. bet Secs. 31 & 32 T. 12 S. R 6 W.
Set a stone 16" x 18" x 24", high point for corner set from Fir 30" N 10° E 1.22 3/4 chs.
Fir 15" in dia. bears N 70° W. .174 chs..
" 4" " " " N 29 1/2° W. .663 " "
Witnesses Carl Peterson and C.R. Huffman March 10, 1926.

Most east S. E. corner of David Belcher Cl 41, Twp. 14-5

2285

Reestablishment by W. C. Galloway

November 10, 1913

Set 1 $\frac{1}{4}$ " pipe 10" under the surface, original corner

Oak 20" in diam bears N 70° 45' W

5.49 chains(standing

Oak 12" in diam bears N 34° 35' W

4.294 chains

Witness James M. Herron