

148240600

DATE 12/01/2020TOWNSHIP 14 SOUTH, RANGE 8 WEST, WILLAMETTE MERIDIAN; SECTION 5 CORNER SOUTH 1/4
DONATION LAND CLAIM N/A CORNER N/A**COMMON CORNER(S):**

NORTH 1/4 CORNER SECTION 8

RECORDS (INFORMATION IN *BOLD ITALICS* IS COUNTY STAFFS' INTERPRETATION OF THE RECORD)

BASED ON EXTENSIVE RESEARCH AND RECOVERY OF EVIDENCE, THIS OFFICE HAS DETERMINED THAT MOST GENERAL LAND OFFICE SURVEYORS IN BENTON COUNTY BEFORE 1890 MEASURED TO THE FACE OF BEARING TREES.

- [01] GENERAL LAND OFFICE (GLO) NOTES BY DENNIS HATHORN, D.S., DATED DECEMBER 5, 1856. *SET POST FROM WHICH A FIR 60" DIA BEARS N36°E, 68 LINKS (44.88 FEET); VINE MAPLE 5" DIA BEARS SOUTH, 29 LINKS (19.14 FEET).*
- [02] BENTON COUNTY SURVEY NO. 2305 FIELD NOTES BY MARTIN L. BEYERLEIN, D.C.S., DATED SEPTEMBER 11, 1951. *SET 3/4" ROD. FIR 88" DIA (GLO BT) BEARS N36°E, 0.680 CHAINS (44.88 FEET), TO PITCH SEAM IN 100 YEARS; MAPLE 26" DIA BEARS S87°40'E, 0.563 CHAINS (37.16 FEET), MARKED "CS 55 BT"; FIR 32" DIA BEARS N33°10'E, 0.480 CHAINS (31.68 FEET), MARKED "CS 55 BT"; FIR 40" DIA BEARS S16°30'W, 1.004 CHAINS AT 15°14', (63.95 FEET), MARKED "CS 55 BT", ALDER 18" DIA AGAINST SOUTH SIDE OF FIR.*
- [03] BENTON COUNTY SURVEY NO. 2305 BY MARTIN L. BEYERLEIN, D.C.S., AND CURTIS C. HANSON, C.S., DATED SEPTEMBER, 1951. *SET 3/4" ROD. FIR 88" DIA (GLO BT) BEARS N36°E, 0.68 CHAINS (44.88 FEET), STANDING; MAPLE 26" DIA (CSBT) BEARS S87°40'E, 0.563 CHAINS (37.16 FEET); FIR 32" DIA (CSBT) BEARS N33°10'E, 0.480 CHAINS (31.68 FEET); FIR 40" DIA (CSBT) BEARS S16°30'W, 0.969 CHAINS, (63.95 FEET).*
- [04] BENTON COUNTY CORNER RESTORATION BOOK NO. 1, PAGE 250, BY MARTIN L. BEYERLEIN, D.C.S., NO DATE GIVEN. *SET 3/4" ROD. FIR 60" DIA (GLO BT) BEARS N36°E, 0.68 CHAINS (44.88 FEET), STANDING; MAPLE 26" DIA (CSBT) BEARS S87°40'E, 0.563 CHAINS (37.16 FEET); FIR 32" DIA (CSBT) BEARS N33°10'E, 0.480 CHAINS (31.68 FEET); FIR 40" DIA (CSBT) BEARS S16°30'W, 0.969 CHAINS, (63.95 FEET).*
- [05] BENTON COUNTY CORNER RESTORATION NO. 2660. *TRANSCRIBED FROM RECORD [04] AND MAY CONTAIN ERRORS AND/OR OMISSIONS.*
- [06] BENTON COUNTY MAP NO. 14-8-00003 BY W. C. GALLOWAY, C.S., DATED APRIL 30, 1918. *3/4" ROD. FIR 88" DIA (GLO BT) BEARS N36°E, 0.68 CHAINS (44.88 FEET), STANDING; MAPLE 26" DIA (CSBT) BEARS S87°40'E, 0.563 CHAINS (37.16 FEET); FIR 32" DIA (CSBT) BEARS N33°10'E, 0.480 CHAINS (31.68 FEET); FIR 40" DIA (CSBT) BEARS S16°30'W, 0.969 CHAINS, (63.95 FEET).*
- [07] BUREAU OF LAND MANAGEMENT (BLM) NOTES BY C. ALBERT WHITE, HARVEY E. WOFFORD AND STEPHEN D. ALBRIGHT, CADASTRAL SURVEYORS, DATED MAY 21, 1970. *THE 1/4 SECTION CORNER MONUMENTED WITH AN IRON ROD, 3/4" DIA, FIRMLY SET, EXTENDING 3" ABOVE GROUND, FROM WHICH A SAWED FIR STUMP 88" DIA (GLO BT) BEARS N36°E, 68 LINKS (44.88 FEET), NO MARKS VISIBLE ON OPENED BLAZE; FIR SNAG 32" DIA (CSBT) BEARS N33°W, 48 LINKS (31.68 FEET), WITH SCRIBE MARK "5" VISIBLE ON OPEN DOUBLE BLAZE; ROOT HOLE (CSBT) BEARS S16-1/2°W, 97 LINKS (64.02 FEET), WITH A DOWN FIR ALONGSIDE, 40" DIA, NO MARKS VISIBLE. AT THE CORNER POINT SET AN IRON POST, 28" LONG, 2-1/2" DIA, 24" IN THE GROUND, WITH BRASS CAP MARKED "T14S R8W S5 1/4 S8 1970" FROM WHICH A FIR 40" DIA BEARS N46-1/2°W, 176 LINKS (116.16 FEET), MARKED "1/4 S5 BT"; ALDER 6" DIA BEARS S22-1/2°W, 103 LINKS (67.98 FEET), MARKED "1/4 S8 BT" ON BARK BLAZE. RESET IRON BAR ALONGSIDE IRON POST.*
- [08] REPORT TO CADASTRALS OF BEARING TREES CUT AND TREATED DATED JULY, 1980. *DOUGLAS FIR 40" DIA (BLM BT) BEARS N46-1/2°W, 116.0 FEET, HEALED FACE, CUT, TREATED AND CAPPED.*
- [09] BENTON COUNTY CORNER RESTORATION NO. 3366. *TRANSCRIBED FROM RECORD [08] AND MAY CONTAIN ERRORS AND/OR OMISSIONS.*
- [10] BENTON COUNTY SURVEY NO. 8676 BY JIM S. PETERSON, P.L.S., DATED JANUARY 15, 1993. *FOUND 1970 3" BLM BRASS CAP MARKED "T14S R8W S5 1/4 S8 1970".*
- [11] BENTON COUNTY SURVEY NO. 9260 BY JIM S. PETERSON, P.L.S., DATED NOVEMBER 11, 1997. *FOUND 3" BRASS CAP (BLM 1970).*

FIRM/AGENCY: BENTON COUNTY SURVEYOR'S OFFICE
ADDRESS: 360 S.W. AVERY AVE., CORVALLIS, OR 97333; PH. 541-766-6821
RESEARCH BY: DAVID L. MALONE, P.L.S.
DATA ENTRY BY: SAME

BENTON COUNTY SURVEYORS OFFICE - CORNER RESTORATION

3366


T 14 S, R 8 W, W. B. & M., BENTON COUNTY, OREGON

SECTION 5

REPORTED BY Tom Tomczyk

TITLE BLM

DATE 7/80



● OFFICIAL CORNER FOUND

○ CORNER SET

1/4 CORNER COMMON TO SEC. 5 & 8

IS _____ DESCRIBE _____

ADDITIONAL INFORMATION

BT CUT & TREATED PER TERMS
OF TIMBER SALE CONTRACT
TSP-139 "DIGGER MTN"

LEGIBLE MARKS ON BEARING OBJECTS

	HEALED FACE		
	STUMP		
KIND	D. FIR		
SIZE	40"		
BEARING	N 46 1/2° W		
DISTANCE	116.0'		
BT TAG POSTED	Y		

OVER

BENTON COUNTY CORNER RESTORATION BOOK NO. 1

C.S. #55
M.L. Boyerlein
Cliff Ames

Sec. Cor. to Secs. 5, 6, 7 & 8, Twp. 14 S., R. 8 W.

Set $\frac{3}{4}$ " rod

Fir 50" S. 10° W. 0.53 Sneg sth.
" " N. 29° 36' W. (N. 28° W.) 0.94 sth.
" " N. 87° 24' E. (N. 87° E) 0.75 "
" 4" S. 20° 41' W. 0.223
" 2" S. 58° 52' E. 0.173

$\frac{1}{4}$ Sec. Cor. between Secs. 5 & 8, Twp. 14 S., R. 8 W.

Set $\frac{3}{4}$ " rod

Fir 60" N. 36° E. 0.68 sth
" 32" N. 33° 10' E. 0.480
" 40" S. 16° 30' W. 0.969
Maple 26" S. 87° 40' E. 0.563

$\frac{1}{4}$ Sec. Cor. between Secs. 8 & 17, Twp. 14 S., R. 8 W.

Set $\frac{3}{4}$ " rod

Fir 17" N. 46° 19' E. 1.855
" 31" S. 68° 54' E. 2.973

$\frac{1}{4}$ Sec. Cor. between Secs. 7 & 8, Twp. 11 S., R. 6 W.

Set Stone 10" x 10" x 12"

Red Fir 48" N. 10° E. 0.497
" 54" S. 18° W. 0.591

C.S. #24
FMVV
11-12-08



$\frac{1}{4}$ -Section corner between sections 5 and 8, Twp. 14 S., R. 8 W.

2660

Reestablishment by M. L. Beyerlein

1951

Set $\frac{3}{4}$ " rod

Fir 60" in diam bears N 36° E	0.68 chains
Fir 32" in diam bears N 33° 10' E	0.480 chains
Fir 40" in diam bears S 16° 30' W	0.969 chains
Maple 26" in diam bears S 87° 40' E	0.563 chains

Witness Cliff Ames