

S. HARDIN 1978

18

294

Dependent Resurvey, Portion of Subdivisional Lines,
T. 15 S., R. 8 W., Willamette Meridian, Oregon

CHAINS
20.105
158400540



The 1/4 sec. cor. of secs. 9 and 10, perpetuated and recorded by W. C. Galloway, County Surveyor, in 1943, monumented with an iron bolt, 1 in. diam., firmly set, projecting 6 ins. above ground, alongside of which is lying the original sandstone, 14 x 10 x 5 ins., loosely set, projecting 6 ins. above ground, mkd. 1/4 S on W. face, from which bearing objects described by Galloway:

A stone, 16 x 10 ins., projecting 14 ins. above ground, bears S. 5° W., 16 lks. dist.

A stone, 30 x 26 ins., projecting 6 ins. above ground, bears S. 80 1/2° W., 66 1/2 lks. dist.

At the corner point

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 20 ins. in the ground, to solid rock, and in a stone collar, 1 1/2 ft. base, to top, with brass cap mkd.

T 15 S R 8 W
1/4
S 9 | S 10
1978

from which

A fir, 15 ins. diam., bears N. 48° E., 156 1/2 lks. dist., mkd. 1/4 S10 ET.

A fir, 10 ins. diam., bears N. 85° W., 47 lks. dist., mkd. 1/4 S9 BT.

Deposit corner stone and reset iron bolt alongside iron post.

Land, rolling bottom land.

Soil, sandy loam.

Timber, fir, hemlock, cedar, maple, and alder; undergrowth, vine maple, salmonberry, salal, Oregon grape, and fern.

From the cor. of secs. 2, 3, 10, and 11.

N. 87° 08' W., bet. secs. 3 and 10.

Ascend 5 ft. along broken N. slope, through heavy timber and dense undergrowth.

3.75 Spur, slopes NW.; desc. 420 ft. over broken W. slope.

37.10 Coal Creek, 15 lks. wide, course N. 30° W.; asc. 25 ft. over NE. slope.

39.65 The 1/4 sec. cor. of secs. 3 and 10, perpetuated and recorded by W. C. Galloway, County Surveyor, in 1943, determined at record distance from the remains of the original bearing trees:

An alder, 25 ins. diam., bears N. 4° W., 27 lks. dist., no marks visible. (Record, N. 5° E.)

A sawed fir stump, 60 ins. diam., bears S. 37 1/2° W., 190 lks. dist., with scribe mark B visible on opened blaze.