C.S. # 456

F.B. 17-53

CHAINS

53

C.S. 456
F/B 17, Pg. 53

Lincoln School - Calculation + Description

CS 456

Description of

Compromised School Tract

Beginning at a 1 1/4" pipe which is in the center of the State Road, said pipe being 34.39 chains South and 39.69 chains East of the northwest corner of the J. C. Alexander D. L. C. No. 46, Township 12 South Range 5 West of the Willamette Meridian in Benton County, Oregon, and running thence East 5.155 chains to a 1" pipe, thence North 4.00 chains to a 1" pipe, thence West 4.845 chains to a 1" pipe, thence South 4°26' West 4.012 chains to the place of beginning, containing 2 acres.