



Pipe placed to 21
 N 50° 56' W - 29.486 ch
 + N 35° 14' W 26.845 ch
 from SE cor. D.L.C. 37

Fd 1" i.p. at fence end as shown on C.S. 81. This pipe was shown to Mr. R. B. Robinson by Mr. G. Armstrong in 1940 as the northeast corner of Mr. Robinson's land.

NW cor of 2nd parcel in Deed 99/51a

Bearings based on S 35° 14' E line between 3/4" i.p. on S. line of D.L.C. 37 and 1/2" i.p. East 6.845 ch., S 51° 34' E 19.772 ch., and South 26.896 ch. of the NW cor. of D.L.C. 37 as shown on C.S. 81 and unfiled survey by C. Cook done for Parker Real Estate

Fence, undisturbed since 1912, runs coincident with line between pipes.

Fd 1" i.p. at fence end as shown on C.S. 81.

SW cor of 2nd parcel in Deed 99/51a

County Road
 south line of deed 165/582
 S 46° 30' E 120' max or less

CS 3269
 Survey
 for
PARKER REAL ESTATE

in
 D.L.C. 37, T. 11 S., R. 5 W., W.M.

Scale: 1 in. = 30 ft
 May 1959

C. W. Dane
 Corvallis, Ore

REGISTERED
OREGON
 LAND SURVEYOR

C. W. Dane

MAY 10, 1957
C. W. DANE
 396

Survey by transit and 10-var tape
 Error of closure 1/5000