



U.S. Highway 99 West
120 Ft R/W (A.C. surface)

5630
RECORD OF SURVEY
FOR
THE SOUTHLAND CORPORATION
IN THE SW 1/4 SEC 24
T11N R5W W1N1, Benton County, OR.

I hereby certify to purchaser and Lloyds Title Insurance Corporation that this survey, made under my supervision on Dec. 12, 1973, correctly shows the location of buildings and other structures to the property lines of the land indicated hereon; that the walls of said buildings are dumb and that there are no encroachments of adjoining buildings or structures onto said land, nor overlap of buildings or structures except as shown.

Scale: 1 inch = 10 feet
Surveyed Dec. 12, 1973
Bearings based on east R/W line of North 3rd St.
B.M. Brass cap in curb SW corner
9th and Walnut. Elev. 229.29± C.M. of
Corvallis datum.
Note: Entire area has A.C. pavement, except east of building.
Location Numbers 2242-17105
G.F.N. 10797

REGISTERED
PROFESSIONAL
LAND SURVEYOR
Richard W. Fall
OREGON
NOVEMBER 4, 1955
RICHARD W. FALL
357

D.I.E. COR. OF HIG. LANE
D.I.E. NO. 37175.854