
CS # 3732

See corner restoration 11-7
¼ corner between section 3
and section 4.

C.S. 3732

BRUCE STARKER
FORESTER
5250 PHILMATH ROAD
WAVERLY 9-6565
CORVALLIS, OREGON

January 29, 1963

C.C. Hanson
County Surveyor
Benton County Court House
Corvallis, Oregon

Dear Curtiss;

Following are my notes on the remark of the $\frac{1}{4}$ Corner common to sections 3 and 4 in T. 11 S., R. 7 W.

Found in place:

Original fir bearing tree stumps

$\frac{1}{2}$ " galvanized iron pipe set by W.C. Galloway April 16, 1913

I marked

Fir 10" S 82°W .305 ch. with bark scribed "BT" at base. Tree already marked with upper cruiser mark \sphericalangle facing corner

Corner is located under North - South barbed wire fence. *Nw Slope.*

Very truly yours

Bruce Starker

Bruce Starker

