

C.S. # 188 F/B 16.19.36-37  
 C.S. 19.437

36<sup>th</sup> Road Survey #153 - Re Survey  
 W. Beg. N.E. con. of Maurice Hedges Chk

Set 1 1/4" galv pipe two stumps

Double Gash 22" N. 59°10' E. 1199 chs.

Went to N.W. cor. and full

East on line 5°35' 8000

1°50' 8000

1" pipe on road 5928

2 157451

3 11741

4 10212

5 9178

N.E. con. 11,258

S/E. 171

South correction N.W.

6 6906

7 2982

8 2590

9 15810

10 5691

11 7506

12 10201

19 457

41 + 207

W. 341

E. 1/4 of Q. 116" N. 88° 45" W. 33824.5

April 10, 1914.  
 Ward Wilkes

099  
 084

17478  
 5565

23043

5966  
 1094

7000

57228

17478  
 5552

23030

015075

171 E.

582 W.

411 W.

103 W.

576 W.

319 E.

257 W.

00311 E 11"

7570

2175

950

625

1850

825

725

31967

54930  
 1067

15851

11741

10412

9178

46982

31967

46960

46982

31967

46960

46982

31967

46960

46982

31967

46960

46982

31967

46960

46982

31967

46960

46982

31967

46960

46982

37

13

14

SF Maurice Hodges c/w + 018' ?  
Striking w/ 1 1/2" pipe 319

2240'

4917'

offset w/ +  
2 Right 25'

582  
5666  
17.008

offset  
165 ft.  
SE cor  
C#46

5666
17.008
22.674
1.018
23.692
2.227
25.919
108.559
43.331
158.85
1647.08

22.655
4.912
27.567
41.08
27.550

5493.0
491.2
5984.2
22.655
8249.7
321.997
27250.0